

Register entry, as of 28 October 2026

Listed for sale

Record ID 1522d0091c0c

2013 Ram 1500 ST

4.7 L, 8 cylinders · 4x2 · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3C6

WMI 1-3

Ram · CHRYSLER DE MEXI...

JR6DP

DESCRIPTOR 4-8

1500 · 4.7 L

0

CHECK 9

Verified

D

YEAR 10

2013

G

PLANT 11

Saltillo

571114

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	4.7 L, 8 cylinders
Make	Ram	Fuel	Gasoline
Model	1500	Drive	4x2
Trim	ST	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Pickup	Plant	Saltillo, Coahuila, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/1500/2013

14 recalls listed by Transport Canada for this model year

Structure 2019441 30 Aug 2019

Issue: On certain trucks equipped with a power locking tailgate, the tailgate may open while driving. If this occurs, cargo that is not secured could fall out of the truck bed and onto the road. Note: This is an expansion of recall U74 (Transport Canada recall 2018-398). Safety Risk: Cargo that falls from the truck bed could create a road hazard for others. Corrective Actions: The company will notify owners by mail and instruct them to take their truck to a dealer to modify the tailgate locking mechanism. Note: This recall supersedes recall 2019-221

Other 2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation "DOT 287" along with the lettering "VMR" (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Powertrain 2017659 21 Dec 2017

On certain vehicles equipped with a steering column gear shifter, the brake transmission shift interlock (BTSI) may become inoperative. This could allow the steering column gear shifter lever to be shifted out of the PARK (P) position without depressing the service brake pedal or having the key in the ignition, which could result in unintended vehicle movement, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect and replace the BTSI as necessary. The Body Control Module (BCM) will also be updated.



Airbag

2017250 10 May 2017

On certain vehicles equipped with Occupant Restraint Controllers (“ORC”) with roll rate sensing, under certain external conditions, a fault may be set relating to rollover sensing that will illuminate the airbag warning light and disable rollover sensing until the vehicle is restarted. A loss of airbags and seatbelt pretensioner deployment when warranted during a rollover crash may increase the risk of injury to vehicle occupants. Correction: Dealers will reprogram the ORC.

Accessories

2016214 12 May 2016

*** This notice is provided for information purposes only as the subject equipment is not regulated under the Motor Vehicle Safety Act ***

Certain Mopar canvas seat covers, sold as aftermarket parts, may not be compatible with vehicles equipped with seat thorax airbags and could impede deployment. This could increase the risk of injury to the seat occupant in a side impact crash where seat thorax airbag deployment is warranted. Correction: FCA Canada will notify owners who may have purchased the Mopar Canvas Seat Covers, and advise them to remove the covers and return them for a refund.

Airbag

2015330 22 Jul 2015

On certain vehicles equipped with Electronic Vehicle Information Centers, the steering wheel wiring harness may wear against the driver frontal airbag retainer spring, potentially resulting in an electrical short which could cause unintended driver frontal airbag deployment. Unintended airbag deployment, in a non-warranted (non-impact) situation, could result in injury and increase the risk of a vehicle crash causing injury and/or property damage. Correction: Dealers will secure the wiring harness and add protective caps to the retainer spring.

8 more on the model-year record, cardog.app/tools/recalls/ram/1500/2013

Listed for the model year, not checked against your VIN. Ram confirms which apply.

Check your VIN with Mopar Canada or call a Ram dealer with your VIN.

www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$15,990^[5], \$2,251 over the median of \$13,739^[4].



Lowest ask	\$7,811
Middle half	\$10,374 – \$16,995
Median ask	\$13,739
This car	\$15,990

Same model year · 36 live listings · as of 28 Oct 2026

OTHER 2013 RAM 1500 LISTINGS ^[5]

Yarmouth, NS · 251,705 km	\$9,995
Kentville, NS · 251,705 km	\$9,995
New Minas, NS · 251,705 km	\$9,995
Middleton, NS · 251,705 km	\$9,995
Yarmouth, NS · 251,705 km	\$9,995
Middleton, NS · 251,705 km	\$9,995



§4 EVENTS

2013	Model year 2013 ^[1] Assembly plant Saltillo, Coahuila, Mexico
3 Dec 2012	Transport Canada recall 2012405 ^[2] Issued for the model year · Lights and instruments
5 Apr 2013	Transport Canada recall 2013106 ^[2] Issued for the model year · Brakes
8 May 2013	Transport Canada recall 2013156 ^[2] Issued for the model year · Visual system
7 Jun 2013	Transport Canada recall 2013201 ^[2] Issued for the model year · Lights and instruments
7 Jun 2013	Transport Canada recall 2013198 ^[2] Issued for the model year · Lights and instruments
4 Jul 2013	Transport Canada recall 2013230 ^[2] Issued for the model year · Other
6 Dec 2013	Transport Canada recall 2013434 ^[2] Issued for the model year · Powertrain
22 Jul 2015	Transport Canada recall 2015330 ^[2] Issued for the model year · Airbag
22 Jul 2015	Transport Canada recall 2015326 ^[2] Issued for the model year · Airbag
12 May 2016	Transport Canada recall 2016214 ^[2] Issued for the model year · Accessories
10 May 2017	Transport Canada recall 2017250 ^[2] Issued for the model year · Airbag
21 Dec 2017	Transport Canada recall 2017659 ^[2] Issued for the model year · Powertrain
21 Aug 2019	Transport Canada recall 2019420 ^[2] Issued for the model year · Other
30 Aug 2019	Transport Canada recall 2019441 ^[2] Issued for the model year · Structure
8 Jul 2026	Listed for sale, Barrie, ON ^[5] G. D. Coates Used Car Superstore · asking \$15,990
27 Oct 2026	Listing last updated ^[5] asking \$15,990



§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 36 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

