Register entry, as of 27 October 2026 Listed for sale Record ID 632de28d20a4

2022 Ram 1500 Tradesman

3.6 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3C6	RR7KG	8	N	G	257997
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ram · CHRYSLER DE MEXI…	1500 · 3.6 L	Verified	2022	Saltillo	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	3.6 L, 6 cylinders
Make	Ram	Fuel	Gasoline
Model	1500	Drive	4WD
Trim	Tradesman	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Pickup	Plant	Saltillo, Coahuila, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/1500/2022

13 recalls listed by Transport Canada for this model year

Seats and restraints

2026371 30 Jul 2026

Issue: On certain trucks, the second-row seat belt anchors may not be properly attached. As a result, the seat belt(s) could detach in a crash. Safety Risk: A seat belt that detaches could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to inspect and, if necessary, secure the second-row seat belt buckle(s) to the body.

Visual system

2026347 16 Jul 2026

Issue: On certain trucks, the passenger-side mirror glass may not be attached properly. As a result, the mirror glass could fall off. Note: This recall only affects certain trucks equipped with a heated trailer tow mirror. Safety Risk: A missing mirror will reduce rear visibility and could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the passenger side mirror glass.

Airbag

2025613 6 Nov 2025

Issue: On a small number of vehicles, the steering column control module may not have been manufactured properly. As a result, the driver-front airbag may not inflate in a crash. Note: This problem would cause the airbag warning light to turn on. Safety Risk: An airbag that is turned off could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the steering column control module.

Visual system

2024596 10 Oct 2024

Issue: On certain trucks, the driver's side mirror glass may not be attached properly. As a result, the mirror glass could fall off. Note: This recall only affects certain trucks equipped with a heated trailer tow mirror. Safety Risk: A missing mirror will reduce rear visibility and could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your truck to a dealership to replace the driver side mirror glass.

Brakes

2024503 5 Sep 2024

Issue: On certain trucks, a software problem could cause the electronic stability control (ESC) system not to work. As a result, the vehicles may not meet certain requirements of Canadian regulations. Note: This problem would cause warning lights for the antilock braking system (ABS), ESC, adaptive cruise control (ACC), and forward collision warning (FCW) to appear on the instrument panel. Safety Risk: An electronic stability control system that doesn't work could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your truck to a dealership to update the antilock braking system (ABS) control module software.

Visual system

2024338 13 Jun 2024

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: For the Grand Cherokee model, this recall affects 2022-2023 Jeep Grand Cherokee and 2021-2023 Grand Cherokee L models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the radio software.

7 more on the model-year record, cardog.app/tools/recalls/ram/1500/2022

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 16 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $39,995[5], $5,000 over the median of $34,995[4].

Lowest ask	$17,999
Middle half	$30,680 – $36,990
Median ask	$34,995
This car	$39,995

Same configuration · 19 live listings · as of 27 Oct 2026

OTHER 2022 RAM 1500 LISTINGS [5]

Fairview, AB · 99,227 km	$34,999
Saskatoon, SK · 141,771 km	$39,995
Prince George, BC · 55,124 km	$45,654
Prince George, BC · 119,318 km	$42,989
Edmonton, AB · 127,479 km	$23,950
Waterloo, ON · 93,250 km	$45,999

§4 EVENTS

2022	Model year 2022[1] Assembly plant Saltillo, Coahuila, Mexico
16 Mar 2021	Transport Canada recall 2021156[2] Issued for the model year · Brakes
9 Jun 2022	Transport Canada recall 2022304[2] Issued for the model year · Visual system
14 Oct 2022	Transport Canada recall 2022584[2] Issued for the model year · Engine
9 Feb 2023	Transport Canada recall 2023047[2] Issued for the model year · Visual system
13 Apr 2023	Transport Canada recall 2023218[2] Issued for the model year · Fuel system
12 May 2023	Transport Canada recall 2023283[2] Issued for the model year · Visual system
28 Sep 2023	Transport Canada recall 2023533[2] Issued for the model year · Visual system
13 Jun 2024	Transport Canada recall 2024338[2] Issued for the model year · Visual system
5 Sep 2024	Transport Canada recall 2024503[2] Issued for the model year · Brakes
10 Oct 2024	Transport Canada recall 2024596[2] Issued for the model year · Visual system
6 Nov 2025	Transport Canada recall 2025613[2] Issued for the model year · Airbag
16 Jul 2026	Transport Canada recall 2026347[2] Issued for the model year · Visual system
30 Jul 2026	Transport Canada recall 2026371[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Swift Current, SK[5] Gauvin Motors Ltd · asking $39,995
27 Oct 2026	Listing last updated[5] asking $39,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 19 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.