Register entry, as of 6 November 2026 Listed for sale Record ID 019483b9797a

2021 Ram 1500 Tradesman

5.7 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3C6	RR7KT	3	M	G	518822
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ram · CHRYSLER DE MEXI…	1500 · 5.7 L	Verified	2021	Saltillo	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	5.7 L, 8 cylinders
Make	Ram	Fuel	Gasoline
Model	1500	Drive	4WD
Trim	Tradesman	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Pickup	Plant	Saltillo, Coahuila, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/1500/2021

14 recalls listed by Transport Canada for this model year

Seats and restraints

2026371 30 Jul 2026

Issue: On certain trucks, the second-row seat belt anchors may not be properly attached. As a result, the seat belt(s) could detach in a crash. Safety Risk: A seat belt that detaches could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to inspect and, if necessary, secure the second-row seat belt buckle(s) to the body.

Visual system

2026347 16 Jul 2026

Issue: On certain trucks, the passenger-side mirror glass may not be attached properly. As a result, the mirror glass could fall off. Note: This recall only affects certain trucks equipped with a heated trailer tow mirror. Safety Risk: A missing mirror will reduce rear visibility and could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the passenger side mirror glass.

Airbag

2025613 6 Nov 2025

Issue: On a small number of vehicles, the steering column control module may not have been manufactured properly. As a result, the driver-front airbag may not inflate in a crash. Note: This problem would cause the airbag warning light to turn on. Safety Risk: An airbag that is turned off could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the steering column control module.

Visual system

2024596 10 Oct 2024

Issue: On certain trucks, the driver's side mirror glass may not be attached properly. As a result, the mirror glass could fall off. Note: This recall only affects certain trucks equipped with a heated trailer tow mirror. Safety Risk: A missing mirror will reduce rear visibility and could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your truck to a dealership to replace the driver side mirror glass.

Brakes

2024503 5 Sep 2024

Issue: On certain trucks, a software problem could cause the electronic stability control (ESC) system not to work. As a result, the vehicles may not meet certain requirements of Canadian regulations. Note: This problem would cause warning lights for the antilock braking system (ABS), ESC, adaptive cruise control (ACC), and forward collision warning (FCW) to appear on the instrument panel. Safety Risk: An electronic stability control system that doesn't work could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your truck to a dealership to update the antilock braking system (ABS) control module software.

Engine

2023221 13 Apr 2023

Issue: Under certain driving conditions, a problem with the powertrain control module (PCM) could cause the engine to stall. Note: This recall only affects trucks equipped with a 5.7 L eTorque engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your truck to a dealership to update the PCM calibration software.


8 more on the model-year record, cardog.app/tools/recalls/ram/1500/2021

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 15 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $25,998[5], $3,696 under the median of $29,694[4].



Lowest ask	$18,994
Middle half	$25,881 – $31,995
Median ask	$29,694
This car	$25,998

Same configuration · 65 live listings · as of 6 Nov 2026

OTHER 2021 RAM 1500 LISTINGS [5]

Etobicoke, ON · 67,711 km	$47,590
Peterborough, ON · 79,238 km	$34,999
New Minas, NS · 128,000 km	$30,995
Ottawa, ON · 185,539 km	$29,999
Kamloops, BC · 177,323 km	$34,995
Sherbrooke, QC · 121,776 km	$35,987

§4 EVENTS

2021 Model year 2021[1]
Assembly plant Saltillo, Coahuila, Mexico

16 Mar 2021	**Transport Canada recall 2021156**[2] Issued for the model year · Brakes
10 Jun 2021	**Transport Canada recall 2021362**[2] Issued for the model year · Other
23 Nov 2021	**Transport Canada recall 2021720**[2] Issued for the model year · Visual system
24 Nov 2021	**Transport Canada recall 2021722**[2] Issued for the model year · Airbag
25 Aug 2022	**Transport Canada recall 2022476**[2] Issued for the model year · Visual system
14 Oct 2022	**Transport Canada recall 2022584**[2] Issued for the model year · Engine
14 Oct 2022	**Transport Canada recall 2022583**[2] Issued for the model year · Seats and restraints
9 Feb 2023	**Transport Canada recall 2023047**[2] Issued for the model year · Visual system
13 Apr 2023	**Transport Canada recall 2023221**[2] Issued for the model year · Engine
5 Sep 2024	**Transport Canada recall 2024503**[2] Issued for the model year · Brakes
10 Oct 2024	**Transport Canada recall 2024596**[2] Issued for the model year · Visual system
6 Nov 2025	**Transport Canada recall 2025613**[2] Issued for the model year · Airbag
16 Jul 2026	**Transport Canada recall 2026347**[2] Issued for the model year · Visual system
30 Jul 2026	**Transport Canada recall 2026371**[2] Issued for the model year · Seats and restraints
3 Nov 2026	**Listed for sale, Brossard, QC**[5] Park Avenue Honda · asking $25,998
6 Nov 2026	**Listing last updated**[5] asking $25,998

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 65 live listings, as of 6 Nov 2026
[5] Live public dealer listings on Cardog, as of 6 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.