Register entry, as of 29 October 2026 Listed for sale Record ID cd4e01fc6cf9

2026 Ram 1500 Sport

3.0 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3C6	SRFVP	5	T	4	155482
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ram · CHRYSLER DE MEXI…	1500 · 3.0 L	Verified	2026	Saltillo	Build sequence

§1 IDENTITY [1]

Model year	2026	Engine	3.0 L, 6 cylinders
Make	Ram	Fuel	Gasoline
Model	1500	Drive	4WD
Trim	Sport	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Pickup	Plant	Saltillo, Coahuila, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/1500/2026

7 recalls listed by Transport Canada for this model year

Visual system — 2026416 — 1 Sep 2026

Issue: On certain vehicles, a software problem could cause the rearview camera not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to update the radio software.

Visual system — 2026396 — 13 Aug 2026

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall also affects Grand Cherokee L models and Grand Wagoneer L models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and send a wireless over-the-air software update to eligible vehicles to update the radio software. Alternatively, you may schedule an appointment to have the update performed at an FCA dealership.

Seats and restraints — 2026371 — 30 Jul 2026

Issue: On certain trucks, the second-row seat belt anchors may not be properly attached. As a result, the seat belt(s) could detach in a crash. Safety Risk: A seat belt that detaches could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to inspect and, if necessary, secure the second-row seat belt buckle(s) to the body.

Lights and instruments

2026320 1 Jul 2026

Issue: On certain vehicles, the headlamp assemblies could cause the parking lamps and daytime running lights (DRLs) not to work, or to flicker. As a result, the vehicles may not meet certain requirements of Canadian regulations. Note: This recall only affects vehicles equipped with premium headlamp assemblies. Safety Risk: Parking lamps and/or daytime running lights (DRLs) that don't work properly could make the vehicle less visible to other road users. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to inspect, and if necessary, replace the headlamp assemblies.

Visual system

2026179 9 Apr 2026

Issue: On certain vehicles, a software problem could cause the instrument panel cluster screen not to display when starting the vehicle or while driving. If this happens, you may not be able to see certain information about the vehicle, including the gear selection, warnings, and tell-tales. Note: This recall only affects vehicles equipped with a 3.5" instrument panel cluster. This recall also affects certain RAM 3500, 4500 and 5500 chassis cab incomplete vehicles. Safety Risk: Warnings, tell-tales and gear selection indicators that don't display could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to update the instrument panel cluster software.

Electrical

2026043 2 Feb 2026

Issue: On certain vehicles, the trailer tow module could fail. As a result, the trailer lights may not work when towing a trailer. This problem could also cause the trailer brakes not to work. Note: This recall also affects certain RAM 3500, 4500 and 5500 chassis cab incomplete vehicles. Safety Risk: Trailer lights that don't work could make the vehicle less visible and cause following drivers not to recognize that the vehicle is braking or intends to turn or change lanes. These issues could increase the risk of a crash. Additionally, a loss of trailer brakes could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the trailer tow module.

1 more on the model-year record, cardog.app/tools/recalls/ram/1500/2026

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $52,989[5], $27,970 under the median of $80,959[4].

Lowest ask	$58,950
Middle half	$74,750 – $86,966
Median ask	$80,959
This car	$52,989

Same configuration · 441 live listings · as of 29 Oct 2026

OTHER 2026 RAM 1500 LISTINGS [5]

Oakville, ON · 0 km	$75,450
Cochrane, AB · 14,615 km	$83,990
Jonquière, QC · 10 km	$82,912
Jonquière, QC · 362 km	$82,412
Jonquière, QC · 10 km	$73,417
Jonquière, QC · 10 km	$73,227

§4 EVENTS

2026	Model year 2026[1] Assembly plant Saltillo, Coahuila, Mexico
1 Dec 2025	Transport Canada recall 2025659[2] Issued for the model year · Visual system
2 Feb 2026	Transport Canada recall 2026043[2] Issued for the model year · Electrical
9 Apr 2026	Transport Canada recall 2026179[2] Issued for the model year · Visual system
1 Jul 2026	Transport Canada recall 2026320[2] Issued for the model year · Lights and instruments
30 Jul 2026	Transport Canada recall 2026371[2] Issued for the model year · Seats and restraints
13 Aug 2026	Transport Canada recall 2026396[2] Issued for the model year · Visual system
1 Sep 2026	Transport Canada recall 2026416[2] Issued for the model year · Visual system
29 Oct 2026	Listed for sale, Trois-Rivières, QC, QC[5] Mercedes-Benz Trois-Rivières · asking $52,989

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 441 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.