Register entry, as of 29 October 2026 Listed for sale Record ID 875fcbb4c63b

# 2026 Ram 2500 Tradesman

6.4 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3C6 | UR5CJ | X | T | G | 328221 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Ram · CHRYSLER DE MEXI… | 2500 · 6.4 L | Verified | 2026 | Saltillo | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2026 | Engine | 6.4 L, 8 cylinders |
| Make | Ram | Fuel | Gasoline |
| Model | 2500 | Drive | 4WD |
| Trim | Tradesman | Maker | CHRYSLER DE MEXICO TOLUCA |
| Body | Pickup | Plant | Saltillo, Coahuila, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/2500/2026

**7** recalls listed by Transport Canada for this model year

### Brakes

2026479 6 Oct 2026

Issue: On certain vehicles, a problem with the steering column control module could cause the electronic stability control (ESC) system not to work. Note: This recall is an expansion of Transport Canada recall no. 2026-192. This problem would cause the electronic stability control (ESC) warning light to turn on. Safety Risk: An electronic stability control system that doesn't work could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the steering column control module.

### Visual system

2026396 13 Aug 2026

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall also affects Grand Cherokee L models and Grand Wagoneer L models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and send a wireless over-the-air software update to eligible vehicles to update the radio software. Alternatively, you may schedule an appointment to have the update performed at an FCA dealership.

### Powertrain

2026225 7 May 2026

Issue: On certain trucks, a software problem could allow the vehicle to exceed the speed rating of the tires. If this happens, there could be a loss of control. Safety Risk: A loss of control could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to update the powertrain control module software.

### Brakes

2026192 16 Apr 2026

Issue: On certain vehicles, a problem with the steering column control module could cause the electronic stability control (ESC) system not to work. Note: This problem would cause the electronic stability control (ESC) warning light to turn on. Safety Risk: An electronic stability control system that doesn't work could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the steering column control module.

### Electrical

2026043 2 Feb 2026

Issue: On certain vehicles, the trailer tow module could fail. As a result, the trailer lights may not work when towing a trailer. This problem could also cause the trailer brakes not to work. Note: This recall also affects certain RAM 3500, 4500 and 5500 chassis cab incomplete vehicles. Safety Risk: Trailer lights that don't work could make the vehicle less visible and cause following drivers not to recognize that the vehicle is braking or intends to turn or change lanes. These issues could increase the risk of a crash. Additionally, a loss of trailer brakes could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the trailer tow module.

### Visual system

2025659 1 Dec 2025

Issue: On certain vehicles, a software problem could cause the instrument panel cluster screen not to display when starting the vehicle or while driving. If this happens, you may not be able to see certain information about the vehicle, including the gear selection, warnings, and tell-tales. Note: This recall only affects vehicles equipped with a 12" instrument panel cluster. This recall also affects certain RAM 3500, 4500 and 5500 chassis cab incomplete vehicles. Safety Risk: Warnings, tell-tales and gear selection indicators that don't display could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to update or replace the instrument panel cluster, as necessary.

1 more on the model-year record, cardog.app/tools/recalls/ram/2500/2026

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $84,620[5], $13,122 over the median of $71,498[4].

| | |
|---|---|
| Lowest ask | $64,988 |
| Middle half | $70,408 – $76,926 |
| Median ask | $71,498 |
| This car | $84,620 |

Same configuration · 19 live listings · as of 29 Oct 2026

### OTHER 2026 RAM 2500 LISTINGS [5]

| | |
|---|---|
| Lévis,QC, QC · 0 km | $110,064 |
| Lévis,QC, QC · 0 km | $94,770 |
| Québec, QC · 0 km | $93,459 |
| Edmonton, AB · 21,315 km | $72,787 |
| Edmonton, AB · 19,147 km | $94,697 |
| Winnipeg, MB · 21,315 km | $64,988 |

## §4 EVENTS

| | |
|---|---|
| 2026 | Model year 2026[1]<br>Assembly plant Saltillo, Coahuila, Mexico |
| 18 Aug 2025 | Transport Canada recall 2025424[2]<br>Issued for the model year · Lights and instruments |
| 1 Dec 2025 | Transport Canada recall 2025659[2]<br>Issued for the model year · Visual system |
| 2 Feb 2026 | Transport Canada recall 2026043[2]<br>Issued for the model year · Electrical |
| 16 Apr 2026 | Transport Canada recall 2026192[2]<br>Issued for the model year · Brakes |
| 7 May 2026 | Transport Canada recall 2026225[2]<br>Issued for the model year · Powertrain |
| 13 Aug 2026 | Transport Canada recall 2026396[2]<br>Issued for the model year · Visual system |
| 5 Sep 2026 | Listed for sale, Paspébiac, QC[5]<br>E.P. Poirier Ltée, Paspébiac · asking $84,620 |
| 6 Oct 2026 | Transport Canada recall 2026479[2]<br>Issued for the model year · Brakes |
| 29 Oct 2026 | Listing last updated[5]<br>asking $84,620 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 19 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.