Register entry, as of 29 October 2026 Listed for sale Record ID 4b17a54c381f

# 2019 Ram 2500 Big Horn

6.7 L, 6 cylinders · 4WD · Pickup · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

| 3C6 | UR5DL | X | K | G | 584163 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Ram · CHRYSLER DE MEXI… | 2500 · 6.7 L | Verified | 2019 | Saltillo | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2019 | Engine | 6.7 L, 6 cylinders |
| Make | Ram | Fuel | Diesel |
| Model | 2500 | Drive | 4WD |
| Trim | Big Horn | Maker | CHRYSLER DE MEXICO TOLUCA |
| Body | Pickup | Plant | Saltillo, Coahuila, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/2500/2019

**15** recalls listed by Transport Canada for this model year

### Airbag

2025658 1 Dec 2025

Issue: On certain trucks, the side curtain airbag inflators may be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could rupture unexpectedly and metal fragments could be propelled toward vehicle occupants. Note: This is an expansion of Transport Canada recall 2025-013. Safety Risk: An airbag inflator that ruptures can create a risk of injury. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the affected side curtain airbag(s).

### Airbag

2025013 16 Jan 2025

Issue: On certain trucks, the side curtain airbag inflators may be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could rupture unexpectedly and metal fragments could be propelled toward vehicle occupants. Note: This recall also affects certain 2016 model year RAM 3500 chassis cab incomplete vehicles. Safety Risk: An airbag inflator that ruptures can create a risk of injury. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the affected side curtain airbag(s).

### Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

### Structure
2022699 8 Dec 2022

Issue: On certain trucks, the tailgate could unlatch and open while driving. If this happens, cargo that is not secured could fall out of the truck bed and onto the road. Safety Risk: Cargo that falls from the truck bed could create a road hazard for others. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your truck to a dealership to inspect the alignment of the tailgate strikers, and adjust them if necessary.

### Brakes
2022108 11 Mar 2022

Issue: On certain vehicles, the warning lamp for the electronic stability control (ESC) system may not turn on when there is a problem with the ESC system. Safety Risk: A driver that is not aware of a problem with the ESC system could have an increased risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update the antilock brake system (ABS) control module software.

### Visual system
2022025 27 Jan 2022

Issue: On certain trucks, the nuts that attach the windshield wiper arms may not have been tightened properly. This could cause the wipers to slip and not clear the windshield properly. Safety Risk: Windshield wipers that do not work properly could affect a driver's visibility. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to tighten the nuts on the windshield wiper arms.

9 more on the model-year record, cardog.app/tools/recalls/ram/2500/2019

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $49,998[5], $10,404 over the median of $39,594[4].

| | |
|---|---|
| Lowest ask | $32,295 |
| Middle half | $36,746 – $45,395 |
| Median ask | $39,594 |
| This car | $49,998 |

Same configuration · 16 live listings · as of 29 Oct 2026

OTHER 2019 RAM 2500 LISTINGS [5]

| | |
|---|---|
| Tillsonburg, ON · 91,987 km | $46,595 |
| Toronto, ON · 264,203 km | $32,295 |
| Nanaimo, BC · 142,569 km | $39,995 |
| St Thomas, ON · 91,987 km | $46,595 |
| Oakville, ON · 91,987 km | $46,595 |
| Grimsby, ON · 91,987 km | $46,595 |

## §4 EVENTS

2019 Model year 2019[1]
Assembly plant Saltillo, Coahuila, Mexico

| | |
|---|---|
| 31 May 2019 | Transport Canada recall 2019258[2]<br>Issued for the model year · Lights and instruments |
| 28 Jun 2019 | Transport Canada recall 2019326[2]<br>Issued for the model year · Fuel system |
| 29 Aug 2019 | Transport Canada recall 2019439[2]<br>Issued for the model year · Brakes |
| 12 Sep 2019 | Transport Canada recall 2019457[2]<br>Issued for the model year · Visual system |
| 24 Jan 2020 | Transport Canada recall 2020025[2]<br>Issued for the model year · Powertrain |
| 6 Apr 2020 | Transport Canada recall 2020145[2]<br>Issued for the model year · Visual system |
| 9 Apr 2020 | Transport Canada recall 2020153[2]<br>Issued for the model year · Structure |
| 25 Sep 2020 | Transport Canada recall 2020456[2]<br>Issued for the model year · Seats and restraints |
| 12 Nov 2021 | Transport Canada recall 2021691[2]<br>Issued for the model year · Fuel system |
| 27 Jan 2022 | Transport Canada recall 2022025[2]<br>Issued for the model year · Visual system |
| 11 Mar 2022 | Transport Canada recall 2022108[2]<br>Issued for the model year · Brakes |
| 8 Dec 2022 | Transport Canada recall 2022699[2]<br>Issued for the model year · Structure |
| 15 Aug 2024 | Transport Canada recall 2024548[2]<br>Issued for the model year · Label |
| 16 Jan 2025 | Transport Canada recall 2025013[2]<br>Issued for the model year · Airbag |
| 1 Dec 2025 | Transport Canada recall 2025658[2]<br>Issued for the model year · Airbag |
| 27 Oct 2026 | Listed for sale, Innisfil, ON[5]<br>400 CHRYSLER DODGE JEEP RAM LTD. · asking $49,998 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $49,998 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 16 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.