Register entry, as of 27 October 2026 Listed for sale Record ID 5b53427c7c3a

# 2022 Ram 2500 Laramie

6.7 L, 6 cylinders · 4WD · Pickup · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

| 3C6 | UR5NL | 3 | N | G | 408459 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Ram · CHRYSLER DE MEXI… | 2500 · 6.7 L | Verified | 2022 | Saltillo | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 6.7 L, 6 cylinders |
| Make | Ram | Fuel | Diesel |
| Model | 2500 | Drive | 4WD |
| Trim | Laramie | Maker | CHRYSLER DE MEXICO TOLUCA |
| Body | Pickup | Plant | Saltillo, Coahuila, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/2500/2022

**11** recalls listed by Transport Canada for this model year

### Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

### Visual system

2024338 13 Jun 2024

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: For the Grand Cherokee model, this recall affects 2022-2023 Jeep Grand Cherokee and 2021-2023 Grand Cherokee L models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the radio software.

### Brakes

2024328 6 Jun 2024

Issue: On certain vehicles, a software problem could cause the electronic stability control (ESC) system not to work. As a result, the vehicles may not meet certain requirements of Canadian regulations. Note: This problem would cause a warning light to display on the instrument panel. Safety Risk: An electronic stability control system that doesn't work could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the antilock braking system (ABS) control module software.

### Visual system

2023533 28 Sep 2023

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the radio software.

### Electrical

2023026 9 Feb 2023

Issue: On certain trucks and chassis-cabs equipped with a 6.7 L Cummins diesel engine, the intake air heater relay could short circuit. This could happen even when the vehicle is parked, and the ignition switch is in the off position. Safety Risk: A short circuit could create a fire risk. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the intake air heater relay. FCA recommends that you should park your vehicle outside and away from other vehicles or buildings until the recall repairs are completed.

### Powertrain

2022644 10 Nov 2022

Issue: On certain trucks, a buildup of heat and pressure inside the transmission could cause fluid to leak from the transmission dipstick tube. Note: This recall only affects trucks equipped with a Cummins 6.7 L diesel engine and a 68RFE automatic transmission. Safety Risk: A transmission fluid leak could create the risk of a fire. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the transmission dipstick and vent assembly.

5 more on the model-year record, cardog.app/tools/recalls/ram/2500/2022

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $61,995[5], $5,095 over the median of $56,900[4].

| | |
|---|---|
| Lowest ask | $28,995 |
| Middle half | $50,999 – $61,995 |
| Median ask | $56,900 |
| This car | $61,995 |

Same model year · 121 live listings · as of 27 Oct 2026

OTHER 2022 RAM 2500 LISTINGS [5]

| | |
|---|---|
| Hamilton, ON · 83,783 km | $64,992 |
| Mississauga, ON · 80,766 km | $65,995 |
| Mississauga, ON · 97,930 km | $56,995 |
| Smiths Falls, ON · 85,847 km | $58,995 |
| Burlington, ON · 76,706 km | $55,988 |
| Bobcaygeon, ON · 106,005 km | $69,899 |

## §4 EVENTS

2022 Model year 2022[1]
Assembly plant Saltillo, Coahuila, Mexico

| | |
|---|---|
| 14 Oct 2021 | Transport Canada recall 2021629[2]<br>Issued for the model year · Electrical |
| 24 Nov 2021 | Transport Canada recall 2021722[2]<br>Issued for the model year · Airbag |
| 11 Mar 2022 | Transport Canada recall 2022108[2]<br>Issued for the model year · Brakes |
| 9 Jun 2022 | Transport Canada recall 2022304[2]<br>Issued for the model year · Visual system |
| 26 Aug 2022 | Transport Canada recall 2022478[2]<br>Issued for the model year · Engine |
| 10 Nov 2022 | Transport Canada recall 2022644[2]<br>Issued for the model year · Powertrain |
| 9 Feb 2023 | Transport Canada recall 2023026[2]<br>Issued for the model year · Electrical |
| 28 Sep 2023 | Transport Canada recall 2023533[2]<br>Issued for the model year · Visual system |
| 6 Jun 2024 | Transport Canada recall 2024328[2]<br>Issued for the model year · Brakes |
| 13 Jun 2024 | Transport Canada recall 2024338[2]<br>Issued for the model year · Visual system |
| 15 Aug 2024 | Transport Canada recall 2024548[2]<br>Issued for the model year · Label |
| 26 Oct 2026 | Listed for sale, Val-d'or, QC[5]<br>Garage Poirier & Fils Ltee · asking $61,995 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 121 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.