

Register entry, as of 28 October 2026

Listed for sale

Record ID f29b9252343f

# 2022 Honda HR-V Sport

1.8 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER <sup>[1]</sup>**3CZ RU6H2 0 N M 103728**

WMI 1-3

Honda De Mexico, S.A. De...

DESCRIPTOR 4-8

HR-V · 1.8 L

CHECK 9

Verified

YEAR 10

2022

PLANT 11

Celaya

SERIAL 12-17

Build sequence

## §1 IDENTITY <sup>[1]</sup>

|            |                       |        |                               |
|------------|-----------------------|--------|-------------------------------|
| Model year | 2022                  | Engine | 1.8 L, 4 cylinders            |
| Make       | Honda                 | Fuel   | Gasoline                      |
| Model      | HR-V                  | Drive  | 4WD                           |
| Trim       | Sport                 | Maker  | HONDA DE MEXICO, S.A. DE C.V. |
| Body       | Sport Utility Vehicle | Plant  | Celaya, Gto, Mexico           |

## §2 OBLIGATIONS <sup>[2]</sup>

[cardog.app/tools/recalls/honda/hr-v/2022](https://cardog.app/tools/recalls/honda/hr-v/2022)

## 2 recalls listed by Transport Canada for this model year

### Visual system

2024305 30 May 2024

Issue: Under certain conditions, the battery voltage could drop when starting the engine. If this happens, the display audio system may not start. As a result, the rearview image will not appear on the display screen when reversing. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall replaces Transport Canada recall no. 2023-041. The software update completed by a Honda dealer during recalls HP35 and HP36 (Transport Canada recall no. 2023-041) may not have been effective. As a result, a second repair is required. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to update the display audio software.

### Visual system

2023041 2 Feb 2023

Issue: Under certain conditions, the battery voltage could drop when starting the engine. If this happens, the display audio system may not start. As a result, the rearview image will not appear on the display screen when reversing. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealership to update the display audio software.

Listed for the model year, not checked against your VIN. Honda confirms which apply.

Check your VIN with Honda Canada or call a Honda dealer with your VIN.

[www.honda.ca/en/recalls](https://www.honda.ca/en/recalls)

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>



## §3 VALUE [4]

This car asks \$28,995<sup>[5]</sup>, \$4,503 over the median of \$24,492<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$14,900            |
| Middle half | \$22,905 – \$27,249 |
| Median ask  | \$24,492            |
| This car    | \$28,995            |

Same configuration · 16 live listings · as of 28 Oct 2026

## OTHER 2022 HONDA HR-V LISTINGS [5]

|                            |          |
|----------------------------|----------|
| Halifax, NS · 22,915 km    | \$24,995 |
| Truro, NS · 22,915 km      | \$24,995 |
| Saint John, NB · 22,915 km | \$24,995 |
| Antigonish, NS · 22,915 km | \$24,995 |
| Antigonish, NS · 22,915 km | \$24,995 |
| Montreal, QC · 44,051 km   | \$23,995 |

## §4 EVENTS

|             |                                                                                             |
|-------------|---------------------------------------------------------------------------------------------|
| 2022        | Model year 2022 <sup>[1]</sup><br>Assembly plant Celaya, Gto, Mexico                        |
| 2 Feb 2023  | Transport Canada recall 2023041 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 30 May 2024 | Transport Canada recall 2024305 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 17 Oct 2026 | Listed for sale, Mississauga, ON <sup>[5]</sup><br>Precision Honda · asking \$28,995        |
| 28 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$28,995                                      |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

## SOURCES

|                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 16 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 28 Oct 2026                     |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                  |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

