

Register entry, as of 28 October 2026

Listed for sale

Record ID e9a313194d22

2020 Honda HR-V Sport

1.8 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3CZ **RU6H2** **3** **L** **M** **106720**

WMI 1-3

Honda De Mexico, S.A. De...

DESCRIPTOR 4-8

HR-V · 1.8 L

CHECK 9

Verified

YEAR 10

2020

PLANT 11

Celaya

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	1.8 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	HR-V	Drive	4WD
Trim	Sport	Maker	HONDA DE MEXICO, S.A. DE C.V.
Body	Sport Utility Vehicle	Plant	Celaya, Guanajuato, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/hr-v/2020

6 recalls listed by Transport Canada for this model year

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Visual system

2024305 30 May 2024

Issue: Under certain conditions, the battery voltage could drop when starting the engine. If this happens, the display audio system may not start. As a result, the rearview image will not appear on the display screen when reversing. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall replaces Transport Canada recall no. 2023-041. The software update completed by a Honda dealer during recalls HP35 and HP36 (Transport Canada recall no. 2023-041) may not have been effective. As a result, a second repair is required. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to update the display audio software.

Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.



Airbag

2024059 1 Feb 2024

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Visual system

2023041 2 Feb 2023

Issue: Under certain conditions, the battery voltage could drop when starting the engine. If this happens, the display audio system may not start. As a result, the rearview image will not appear on the display screen when reversing. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealership to update the display audio software.

Listed for the model year, not checked against your VIN. Honda confirms which apply.

Check your VIN with Honda Canada or call a Honda dealer with your VIN.

www.honda.ca/en/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$21,987^[5], \$992 over the median of \$20,995^[4].



Lowest ask	\$15,988
Middle half	\$18,695 – \$22,495
Median ask	\$20,995
This car	\$21,987

Same configuration · 13 live listings · as of 28 Oct 2026

OTHER 2020 HONDA HR-V LISTINGS ^[5]

Cartierville, QC · 126,397 km	\$18,995
Sarnia, ON · 140,823 km	\$18,661
Kentville, NS · 148,670 km	\$17,999
Sainte-Rose, QC · 61,291 km	\$22,495
Georgetown, ON · 110,353 km	\$20,724
Toronto, ON · 46,604 km	\$25,498



§4 EVENTS

2020	Model year 2020 ^[1] Assembly plant Celaya, Guanajuato, Mexico
2 Feb 2023	Transport Canada recall 2023041 ^[2] Issued for the model year · Visual system
18 Dec 2023	Transport Canada recall 2023679 ^[2] Issued for the model year · Fuel system
1 Feb 2024	Transport Canada recall 2024059 ^[2] Issued for the model year · Airbag
6 May 2024	Transport Canada recall 2024262 ^[2] Issued for the model year · Fuel system
30 May 2024	Transport Canada recall 2024305 ^[2] Issued for the model year · Visual system
21 May 2026	Transport Canada recall 2026251 ^[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Mount Pearl, NL ^[5] Penney Pre-owned · asking \$21,987

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 13 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

