Register entry, as of 7 November 2026 Listed for sale Record ID cd7932b2271f

# 2021 Honda HR-V LX

1.8 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3CZ | RU6H3 | 4 | M | M | 103318 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Honda De Mexico, S.A. De… | HR-V · 1.8 L | Verified | 2021 | Celaya | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 1.8 L, 4 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | HR-V | Drive | 4WD |
| Trim | LX | Maker | HONDA DE MEXICO, S.A. DE C.V. |
| Body | Sport Utility Vehicle | Plant | Celaya, Gto, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/hr-v/2021

**4** recalls listed by Transport Canada for this model year

### Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

### Visual system

2024305 30 May 2024

Issue: Under certain conditions, the battery voltage could drop when starting the engine. If this happens, the display audio system may not start. As a result, the rearview image will not appear on the display screen when reversing. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall replaces Transport Canada recall no. 2023-041. The software update completed by a Honda dealer during recalls HP35 and HP36 (Transport Canada recall no. 2023-041) may not have been effective. As a result, a second repair is required. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to update the display audio software.

### Airbag

2024059 1 Feb 2024

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

### Visual system

2023041 2 Feb 2023


Issue: Under certain conditions, the battery voltage could drop when starting the engine. If this happens, the display audio system may not start. As a result, the rearview image will not appear on the display screen when reversing. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealership to update the display audio software.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $22,891[5], $405 over the median of $22,486[4].




| | |
|---|---|
| Lowest ask | $17,995 |
| Middle half | $20,995 – $22,995 |
| Median ask | $22,486 |
| This car | $22,891 |

Same configuration · 9 live listings · as of 6 Nov 2026

### OTHER 2021 HONDA HR-V LISTINGS [5]

| | |
|---|---|
| Terrebonne, QC · 99,210 km | $21,395 |
| Levis, QC · 102,679 km | $20,995 |
| Kamloops, BC · 121,594 km | $23,698 |
| Boucherville, QC · 27,338 km | $25,990 |
| Pincourt, QC · 157,465 km | $21,342 |
| Joliette, QC · 104,243 km | $20,395 |

## §4 EVENTS

| | |
|---|---|
| 2021 | Model year 2021[1]<br>Assembly plant Celaya, Gto, Mexico |
| 2 Feb 2023 | Transport Canada recall 2023041[2]<br>Issued for the model year · Visual system |

| | | |
|---|---|---|
| 1 Feb 2024 | Transport Canada recall 2024059[2] | Issued for the model year · Airbag |
| 30 May 2024 | Transport Canada recall 2024305[2] | Issued for the model year · Visual system |
| 21 May 2026 | Transport Canada recall 2026251[2] | Issued for the model year · Seats and restraints |
| 25 Oct 2026 | Listed for sale, Drummondville, QC[5] | Honda Drummondville · asking $22,891 |
| 4 Nov 2026 | Listing last updated[5] | asking $22,891 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 9 live listings, as of 6 Nov 2026

[5] Live public dealer listings on Cardog, as of 7 Nov 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.