Register entry, as of 29 October 2026 Listed for sale Record ID 825ecf65b79c

# 2023 Honda HR-V SPORT

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3CZ | RZ2H5 | 4 | P | M | 106994 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Honda De Mexico, S.A. De… | HR-V · 2.0 L | Verified | 2023 | Celaya | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 2.0 L, 4 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | HR-V | Drive | 4WD |
| Trim | SPORT | Maker | HONDA DE MEXICO, S.A. DE C.V. |
| Body | Sport Utility Vehicle | Plant | Celaya, Gto, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/hr-v/2023

**2** recalls listed by Transport Canada for this model year

### Steering

2024588 3 Oct 2024

Issue: On certain vehicles, the steering gearbox may not have been manufactured properly. As a result, there could be a sudden change in steering feel and an increase in steering effort. Safety Risk: A sudden change in steering effort could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to add grease to the steering gearbox and replace the electronic power steering spring.

### Seats and restraints

2023623 22 Nov 2023

Issue: On certain vehicles, the seat belt pretensioner(s) may be missing a rivet. As a result, the seat belt pretensioner(s) may not work properly in a crash. Note: On Accord models, only the driver's side pretensioner could be affected. On HR-V models, both the driver's and passenger's side pretensioners could be affected. Safety Risk: A seat belt pretensioner that doesn't work properly could increase the risk of injury in a crash. Corrective Action: Honda will notify owners by mail and advise you to bring your vehicle to a dealership to inspect the seat belt pretensioner(s). If a rivet is missing, the pretensioner will be replaced.

Listed for the model year, not checked against your VIN. Honda confirms which apply.
Check your VIN with Honda Canada or call a Honda dealer with your VIN.
www.honda.ca/en/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $27,490[5], $405 under the median of $27,895[4].

| | |
|---|---|
| Lowest ask | $22,987 |
| Middle half | $26,750 – $29,548 |
| Median ask | $27,895 |
| This car | $27,490 |

Same configuration · 40 live listings · as of 29 Oct 2026

### OTHER 2023 HONDA HR-V LISTINGS [5]

| | |
|---|---|
| Summerside, PE · 130,311 km | $23,128 |
| Kelowna, BC · 26,862 km | $31,900 |
| Terrebonne, QC · 34,372 km | $30,495 |
| Burlington, ON · 61,377 km | $31,998 |
| Saint John, NB · 118,049 km | $22,995 |
| Dorval, QC · 29,199 km | $31,490 |

## §4 EVENTS

| | |
|---|---|
| 2023 | Model year 2023[1]<br>Assembly plant Celaya, Gto, Mexico |
| 22 Nov 2023 | Transport Canada recall 2023623[2]<br>Issued for the model year · Seats and restraints |
| 3 Oct 2024 | Transport Canada recall 2024588[2]<br>Issued for the model year · Steering |
| 28 Oct 2026 | Listed for sale, Scarborough, ON[5]<br>Roadsport Honda · asking $27,490 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 40 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.