Register entry, as of 28 October 2026 Listed for sale Record ID 57646030244d

2019 Ford Fusion Titanium HEV

2.0 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3FA	6P0RU	1	K	R	156293
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ford Motor Company, Mexi…	Fusion · 2.0 L	Verified	2019	Hermosillo	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.0 L, 4 cylinders
Make	Ford	Fuel	Gasoline
Model	Fusion	Drive	Not in the decode
Trim	Titanium HEV	Maker	FORD MOTOR COMPANY, MEXICO
Body	Sedan	Plant	Hermosillo, State Of Mexico, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/fusion/2019

3 recalls listed by Transport Canada for this model year

Electrical

2025554 10 Oct 2025

This recall was replaced by Transport Canada recall no. 2026-005. Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater.

Visual system

2025360 27 Jun 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the SYNC software.

High voltage

2023355 23 Jun 2023

Issue: On certain Fusion Energi plug-in hybrid electric vehicles (PHEV), the high-voltage battery energy control module could become damaged. If this happens, there could be a loss of power to the wheels or the control module could overheat. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. A battery energy control module that overheats can create the risk of a fire, even while the vehicle is parked and turned off. Corrective Actions: Ford will notify owners by mail. As an interim repair, Ford will advise you to take your vehicle to a dealership to install a fuse block for the battery energy control module. The dealer will also update the BECM software. When the final repairs are available, Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the high-voltage battery. To mitigate the safety risk, Ford advises you not to charge your vehicle until the recall repairs are completed.

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $17,797[5], $299 over the median of $17,498[4].

Lowest ask	$8,995
Middle half	$16,496 – $17,995
Median ask	$17,498
This car	$17,797

Same configuration · 11 live listings · as of 28 Oct 2026

OTHER 2019 FORD FUSION LISTINGS [5]

Belleville, ON · 109,013 km	$13,995
New Westminster, BC · 127,804 km	$19,995
Carignan, QC · 111,175 km	$17,498
Edmonton, AB · 106,445 km	$11,499
Calgary, AB · 117,822 km	$15,995
Pembroke, ON · 148,530 km	$16,000

§4 EVENTS

2019	Model year 2019[1] Assembly plant Hermosillo, State Of Mexico, Mexico
23 Jun 2023	Transport Canada recall 2023355[2] Issued for the model year · High voltage
27 Jun 2025	Transport Canada recall 2025360[2] Issued for the model year · Visual system
10 Oct 2025	Transport Canada recall 2025554[2] Issued for the model year · Electrical
26 Oct 2026	Listed for sale, Kelowna, BC[5] Kelowna Kia · asking $17,797

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 11 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.