

Register entry, as of 29 October 2026

Listed for sale

Record ID e999b36b67cf

2025 Ford Bronco Sport BIG BEND

1.5 L, 3 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3FM CR9BN 4 S R E86570

WMI 1-3

Ford Motor Company, Mexi...

DESCRIPTOR 4-8

Bronco Sport · 1.5 L

CHECK 9

Verified

YEAR 10

2025

PLANT 11

Hermosillo

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	1.5 L, 3 cylinders
Make	Ford	Fuel	Gasoline
Model	Bronco Sport	Drive	4WD
Trim	BIG BEND	Maker	FORD MOTOR COMPANY, MEXICO
Body	Sport Utility Vehicle	Plant	Hermosillo, Sonora, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/bronco-sport/2025

6 recalls listed by Transport Canada for this model year

Suspension

2026259 27 May 2026

Issue: On certain vehicles, the front lower ball joint(s) may not have been installed correctly on the steering knuckle(s). As a result, the front lower ball joint(s) could separate and cause a loss of steering control. Safety Risk: A loss of steering control could create a risk of a crash. Corrective Actions: To reduce the safety risk Ford advises you not to drive your vehicle until the recall repairs are completed. Ford will notify owners by mail and advise you to contact a dealer to arrange for an inspection. The dealer will repair the front steering knuckle(s), as necessary.

Seats and restraints

2026162 1 Apr 2026

Issue: On certain vehicles, the front passenger seat occupant classification system (OCS) may not work properly. As a result, the airbag system may turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause the supplemental restraint system (SRS) malfunction indicator to display on the instrument panel, a warning to display in the driver information center and the airbag indicator light to display "Passenger Airbag OFF". Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the front passenger seat occupant classification sensor.

Engine

2026094 3 Mar 2026

Issue: On certain vehicles, the exhaust gas recirculation (EGR) valve may not have been manufactured properly. As a result, the EGR valve could fail and cause a loss of power to the wheels. Note: This recall only affects certain vehicles equipped with a 1.5 L engine, 2.0 L gas or hybrid engine or 2.3 L engine. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail. The corrective actions for this recall are under development.



Visual system

2025627 14 Nov 2025

Issue: On certain vehicles, a software problem could cause the instrument panel cluster not to display when the vehicle is started. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, warning lights and malfunction tell-tales. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the instrument panel cluster module software.

Engine

2025306 3 Jun 2025

Issue: On certain vehicles, the cylinder head may not have been manufactured properly. As a result, the cylinder head plug(s) could fail. If this happens, engine oil could leak and cause a loss of power to the wheels. Note: This recall only affects certain vehicles equipped with a 1.5 L engine. This recall could also affect certain cylinder heads sold at dealerships as a replacement part. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Oil that leaks onto hot components can create the risk of a fire. Additionally, an oil leak could create a hazard for others and increase the risk of a crash. Corrective Action: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the cylinder head.

Engine

2025281 23 May 2025

Issue: On certain vehicles, the engine block heater could overheat when the block heater is plugged in. Note: This recall only affects certain vehicles equipped with a 1.5 L or 2.0 L engine and a factory-installed block heater. Safety Risk: An engine block heater and/or wiring that overheats or melts could create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to plug in the engine block heater until the recall repairs have been completed. Ford will notify owners by mail. You can choose to have the dealer remove the block heater, or once the final repair is available, Ford will send you another notice to advise you to take your vehicle to a dealership to replace the block heater element. The dealer will also inspect and, if necessary, replace the block heater electrical cord.

Listed for the model year, not checked against your VIN. Ford confirms which apply.


Check your VIN with Ford Canada or call a Ford dealer with your VIN.

www.ford.ca/support/recalls/

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$28,495^[5], \$1,503 under the median of \$29,998^[4].



Lowest ask	\$25,749
Middle half	\$28,995 – \$32,934
Median ask	\$29,998
This car	\$28,495

Same configuration · 203 live listings · as of 28 Oct 2026

OTHER 2025 FORD BRONCO SPORT LISTINGS [5]

Lévis, QC · QC · 64,663 km	\$27,995
Edmonton, AB · 50,715 km	\$38,999
Edmonton, AB · 46,172 km	\$29,999
Edmonton, AB · 10,523 km	\$33,887
Edmonton, AB · 7,180 km	\$41,098
Edmonton, AB · 47,715 km	\$29,999



§4 EVENTS

2025	Model year 2025 ^[1] Assembly plant Hermosillo, Sonora, Mexico
23 May 2025	Transport Canada recall 2025281 ^[2] Issued for the model year · Engine
3 Jun 2025	Transport Canada recall 2025306 ^[2] Issued for the model year · Engine
14 Nov 2025	Transport Canada recall 2025627 ^[2] Issued for the model year · Visual system
3 Mar 2026	Transport Canada recall 2026094 ^[2] Issued for the model year · Engine
1 Apr 2026	Transport Canada recall 2026162 ^[2] Issued for the model year · Seats and restraints
27 May 2026	Transport Canada recall 2026259 ^[2] Issued for the model year · Suspension
17 Sep 2026	Listed for sale, Brossard, QC ^[5] Park Avenue Honda · asking \$28,495
28 Oct 2026	Listing last updated ^[5] asking \$28,495

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 203 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

