Register entry, as of 28 October 2026 Listed for sale Record ID 60d3c73eba17

2023 Ford Maverick XL / XLT / Lariat

2.0 L, 4 cylinders · AWD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3FT	TW8F9	7	P	R	A60349
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ford Motor Company, Mexi…	Maverick · 2.0 L	Verified	2023	Hermosillo	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	2.0 L, 4 cylinders
Make	Ford	Fuel	Gasoline
Model	Maverick	Drive	AWD
Trim	XL / XLT / Lariat	Maker	FORD MOTOR COMPANY, MEXICO
Body	Pickup	Plant	Hermosillo, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/maverick/2023

23 recalls listed by Transport Canada for this model year

Suspension

2026259 27 May 2026

Issue: On certain vehicles, the front lower ball joint(s) may not have been installed correctly on the steering knuckle(s). As a result, the front lower ball joint(s) could separate and cause a loss of steering control. Safety Risk: A loss of steering control could create a risk of a crash. Corrective Actions: To reduce the safety risk Ford advises you not to drive your vehicle until the recall repairs are completed. Ford will notify owners by mail and advise you to contact a dealer to arrange for an inspection. The dealer will repair the front steering knuckle(s), as necessary.

Lights and instruments

2026079 20 Feb 2026

Issue: On certain vehicles, a software problem with the integrated trailer module (ITRM) may cause the trailer lights not to work when towing. This problem could also cause the trailer brakes not to work on certain vehicles. Note: This problem would cause a "Trailer brake module fault" message to be displayed and turn signal telltale to flash rapidly. This recall also affects certain Super Duty incomplete vehicles. Safety Risk: Trailer lights that don't work could make the vehicle less visible and cause following drivers not to recognize that the vehicle is braking or intends to turn or change lanes. These issues could increase the risk of a crash. Additionally, a loss of trailer brakes could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the ITRM software. Alternatively, you may schedule an appointment to have the update performed at a Ford dealership.

Engine

2026072 18 Feb 2026

Issue: On a small number of vehicles, the recall repairs completed by a Ford dealer during recall 25S54 (Transport Canada recall no. 2025-283) may not have been done correctly. As a result, another repair is required. On certain vehicles equipped with a 2.5 L HEV or PHEV engine, a manufacturing problem could lead to an engine failure. In some cases, an engine failure can create the risk of a fire. Safety Risk: An engine failure could cause a fire. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the powertrain control module (PCM) software. To reduce the safety risk, Ford recommends that you should shut off the engine as soon as possible if you hear unusual engine noises, see smoke from the engine compartment, or notice reduced engine power.

Electrical

2026005 9 Jan 2026

Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Note: This recall replaces Transport Canada recall no. 2025-554. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater. Alternatively, owners can choose to have the dealership permanently disable the engine block heater.

Electrical

2025554 10 Oct 2025

This recall was replaced by Transport Canada recall no. 2026-005. Issue: On certain vehicles, the engine block heater could leak coolant. If this happens, the block heater could short circuit when it's plugged in. Safety Risk: A short circuit can create the risk of a fire. Corrective Actions: To reduce the safety risk, Ford advises you not to use the engine block heater until the recall repairs have been completed. Ford will notify owners by mail and advise you to take your vehicle to a dealership to replace the block heater.

Visual system

2025360 27 Jun 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the SYNC software.

17 more on the model-year record, cardog.app/tools/recalls/ford/maverick/2023

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 21 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $37,995[5], $4,259 over the median of $33,736[4].

Lowest ask	$26,845
Middle half	$30,895 – $35,995
Median ask	$33,736
This car	$37,995

Same configuration · 32 live listings · as of 28 Oct 2026

OTHER 2023 FORD MAVERICK LISTINGS [5]

Selkirk, MB · 23,962 km	$36,998
Mississauga, ON · 47,937 km	$33,477
Leamington, ON · 47,937 km	$33,477
St-Jean-Sur-Richelieu, QC · 39,417 km	$33,995
Essex, ON · 47,937 km	$33,477
Toronto, ON · 47,937 km	$33,600

§4 EVENTS

2023	Model year 2023[1] Assembly plant Hermosillo, Mexico
13 Mar 2023	Transport Canada recall 2023128[2] Issued for the model year · Lights and instruments
29 May 2023	Transport Canada recall 2023309[2] Issued for the model year · Engine
15 Dec 2023	Transport Canada recall 2023671[2] Issued for the model year · Lights and instruments
23 Feb 2024	Transport Canada recall 2024125[2] Issued for the model year · Lights and instruments
25 Mar 2024	Transport Canada recall 2024192[2] Issued for the model year · Tires
26 Apr 2024	Transport Canada recall 2024246[2] Issued for the model year · Lights and instruments
10 May 2024	Transport Canada recall 2024270[2] Issued for the model year · Powertrain
12 Aug 2024	Transport Canada recall 2024461[2] Issued for the model year · Visual system
13 Sep 2024	Transport Canada recall 2024524[2] Issued for the model year · Visual system
8 Nov 2024	Transport Canada recall 2024692[2] Issued for the model year · Visual system
22 Nov 2024	Transport Canada recall 2024714[2] Issued for the model year · Visual system
14 Feb 2025	Transport Canada recall 2025086[2] Issued for the model year · Lights and instruments
17 Feb 2025	Transport Canada recall 2025081[2] Issued for the model year · Lights and instruments
2 Mar 2025	Transport Canada recall 2025108[2] Issued for the model year · Powertrain
2 Mar 2025	Transport Canada recall 2025102[2] Issued for the model year · Lights and instruments
14 Mar 2025	Transport Canada recall 2025139[2] Issued for the model year · Electrical
23 May 2025	Transport Canada recall 2025283[2] Issued for the model year · Engine

27 Jun 2025	Transport Canada recall 2025360[2] Issued for the model year · Visual system
10 Oct 2025	Transport Canada recall 2025554[2] Issued for the model year · Electrical
9 Jan 2026	Transport Canada recall 2026005[2] Issued for the model year · Electrical
18 Feb 2026	Transport Canada recall 2026072[2] Issued for the model year · Engine
20 Feb 2026	Transport Canada recall 2026079[2] Issued for the model year · Lights and instruments
27 May 2026	Transport Canada recall 2026259[2] Issued for the model year · Suspension
19 Jul 2026	Listed for sale, Sorel-Tracy, QC[5] Honda Sorel Tracy · asking $37,995
28 Oct 2026	Listing last updated[5] asking $37,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 32 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.