Register entry, as of 28 October 2026 Listed for sale Record ID c0e1a3d1a427

2021 GMC Terrain SLE

1.5 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3GK	ALTEV	X	M	L	362903
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
GMC · GENERAL MOTORS…	Terrain · 1.5 L	Verified	2021	San Luis Potosi	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	1.5 L, 4 cylinders
Make	GMC	Fuel	Gasoline
Model	Terrain	Drive	AWD
Trim	SLE	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	San Luis Potosi, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/gmc/terrain/2021

2 recalls listed by Transport Canada for this model year

Seats and restraints

2023279 11 May 2023

Issue: The coating may be too thick on the connection bars for the lower universal anchorage system (UAS) for securing a child or booster seat in the rear seat. As a result, you may not be able to properly attach a child seat in the rear seat using the UAS. Safety Risk: A child seat that isn't properly attached could increase the risk of injury in a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to inspect the bars for the lower universal anchorage system (UAS) in the rear seat. If necessary, the dealer will remove and replace the finish coating on lower anchorage bars. General Motors recommends to install child seats using the rear seat belts, as described in the vehicle owner's manual and child-seat manufacturer's installation guide, until the recall repairs have been completed.

Tires

2021489 5 Aug 2021

Issue: Certain vehicles were built with tires that may have a manufacturing defect. As a result, the tire tread could separate while driving. Note: This recall only affects certain Hankook tires with a date code of 0521, and a specific internal bar code. Safety Risk: A tire tread separation could affect vehicle handling and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to inspect and replace the tires, as necessary.

Listed for the model year, not checked against your VIN. GMC confirms which apply.
Check your VIN with GMC Canada or call a GMC dealer with your VIN.
www.gmccanada.ca/en/ownercenter/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $25,789[5], $5,391 over the median of $20,398[4].



Lowest ask	$12,995
Middle half	$19,497 – $22,455
Median ask	$20,398
This car	$25,789

Same configuration · 28 live listings · as of 28 Oct 2026

OTHER 2021 GMC TERRAIN LISTINGS [5]

Kamloops, BC · 48,184 km	$25,740
Toronto, ON · 136,263 km	$17,768
Haliburton, ON · 44,223 km	$22,995
Penticton, BC · 93,456 km	$22,995
Ottawa, ON · 84,607 km	$21,987
Kamloops, BC · 48,184 km	$25,740

§4 EVENTS

2021	Model year 2021[1] Assembly plant San Luis Potosi, Mexico
5 Aug 2021	Transport Canada recall 2021489[2] Issued for the model year · Tires
11 May 2023	Transport Canada recall 2023279[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Chilliwack, BC[5] Bannister GM Chilliwack · asking $25,789
27 Oct 2026	Listing last updated[5] asking $25,789

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 28 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.