

Register entry, as of 27 October 2026

Listed for sale

Record ID 3385d05fd3b4

2020 GMC Terrain Denali

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**3GK** **ALXEX** **3** **L** **L** **344296**

WMI 1-3

GMC · GENERAL MOTORS...

DESCRIPTOR 4-8

Terrain · 2.0 L

CHECK 9

Verified

YEAR 10

2020

PLANT 11

San Luis Potosi

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2020	Engine	2.0 L, 4 cylinders
Make	GMC	Fuel	Gasoline
Model	Terrain	Drive	AWD
Trim	Denali	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	San Luis Potosi, Mexico

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/gmc/terrain/2020

2 recalls listed by Transport Canada for this model year

Seats and restraints

2023279 11 May 2023

Issue: The coating may be too thick on the connection bars for the lower universal anchorage system (UAS) for securing a child or booster seat in the rear seat. As a result, you may not be able to properly attach a child seat in the rear seat using the UAS. Safety Risk: A child seat that isn't properly attached could increase the risk of injury in a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to inspect the bars for the lower universal anchorage system (UAS) in the rear seat. If necessary, the dealer will remove and replace the finish coating on lower anchorage bars. General Motors recommends to install child seats using the rear seat belts, as described in the vehicle owner's manual and child-seat manufacturer's installation guide, until the recall repairs have been completed.

Powertrain

2020520 29 Oct 2020

Issue: On certain vehicles, the start-stop accumulator in the transmission may be missing bolts. As a result, transmission fluid could leak and eventually cause the transmission to stop working. If this happens, there could be a loss of power to the wheels. Safety Risk: A transmission fluid leak onto a hot surface can create the risk of a fire. Additionally, a loss of power to the wheels could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the transmission start-stop accumulator. It will be replaced if any bolts are found missing.

Listed for the model year, not checked against your VIN. GMC confirms which apply.
Check your VIN with GMC Canada or call a GMC dealer with your VIN.

www.gmccanada.ca/en/ownercenter/recallsUnited States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$23,995^[5], \$2,000 over the median of \$21,995^[4].



Lowest ask	\$16,995
Middle half	\$20,982 – \$23,374
Median ask	\$21,995
This car	\$23,995

Same configuration · 14 live listings · as of 27 Oct 2026

OTHER 2020 GMC TERRAIN LISTINGS [5]

Alliston, ON · 92,270 km	\$19,977
Carbonear, NL · 71,217 km	\$19,995

§4 EVENTS

2020	Model year 2020 ^[1] Assembly plant San Luis Potosi, Mexico
29 Oct 2020	Transport Canada recall 2020520 ^[2] Issued for the model year · Powertrain
11 May 2023	Transport Canada recall 2023279 ^[2] Issued for the model year · Seats and restraints
27 Oct 2026	Listed for sale, Weyburn, SK ^[5] Great Plains Ford Sales · asking \$23,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same configuration, 14 live listings, as of 27 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 27 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

