Register entry, as of 29 October 2026 Listed for sale Record ID 06424daa4e0f

2014 Chevrolet Trax 1LT

1.4 L, 4 cylinders · FWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3GN	CJLEB	4	E	L	174452
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Trax · 1.4 L	Verified	2014	San Luis Potosi	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	1.4 L, 4 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Trax	Drive	FWD
Trim	1LT	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	San Luis Potosi, Guanajuato, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/trax/2014

6 recalls listed by Transport Canada for this model year

Airbag

2016439 9 Sep 2016

On certain vehicles, the sensing and diagnostic module (SDM), which controls airbag and pretensioner deployment, contains a software defect which may prevent the deployment of frontal airbags and pretensioners in certain circumstances. Failure of frontal airbags and seatbelt pretensioners to deploy in a crash (when warranted) could increase the risk of injury. Correction: Dealers will reflash the SDM with new software. In vehicles with any previous deployment events recorded in the SDM, the dealers will replace the existing SDM with a new SDM containing the latest software. Note: This recall affects 2014-2017 model year Sierra LD/Silverado LD models and 2015-2016 model year Sierra HD/Silverado HD model vehicles.

Electrical

2016191 28 Apr 2016

Certain vehicles equipped with a "Bring Your Own Media" (BYOM) radio may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 114 - Theft Protection and Rollaway Protection. The radio software may fail to provide an audible warning/reminder chime that meets the requirements of the standard if the ignition key is left in the off position and the driver delays opening the driver's door for more than 10 minutes, or opens and closes the door several times. The loss of an audible warning when a key is left in the ignition may increase the risk of vehicle theft. Correction: Dealers will reprogram the radio with corrected operating software.

Seats and restraints

2014315 29 Jul 2014

On certain vehicles, the hook bracket assembly for either front seat may have been manufactured with an incomplete weld. If the weld is incomplete and the assembly is exposed to a high load condition, the hook may separate from the seat track. This could increase the risk of occupant injury during a crash. Correction: Dealers will inspect the weld, and if necessary, replace the lower seat track.

Accessories

2014274 3 Jul 2014

On certain vehicles, insulation on the engine block heater power cord may become damaged if the cord is handled during very cold days (temperatures below -25C). This could create an electrical shock hazard, which could result in personal injury. Correction: Dealers will replace the block heater cord.

Brakes

2014115 7 Apr 2014

On certain vehicles, the left front brake line may have been routed incorrectly and may come into contact with the transmission cooler outlet pipe, causing abrasion damage which could result in a brake fluid leak. This could increase stopping distances, possibly resulting in a crash causing property damage and/or personal injury. Correction: Dealers will inspect and reroute and/or replace the brake line, as necessary.

Fuel system

2014019 23 Jan 2014

On certain model vehicles, the quick connectors that join the fuel lines to the fuel tank may not have been properly secured. As a result, the fuel line might loosen or disconnect, resulting in a fuel leak. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will inspect, and if necessary, secure the fuel line quick connectors.

Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
www.chevrolet.ca/en/ownercenter/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $6,999[5], $941 under the median of $7,940[4].



Lowest ask	$2,886
Middle half	$5,996 – $9,981
Median ask	$7,940
This car	$6,999

Same model year · 22 live listings · as of 29 Oct 2026

OTHER 2014 CHEVROLET TRAX LISTINGS [5]

Longueuil, QC · 139,158 km	$9,955
Sundridge, ON · 171,768 km	$6,495
London, ON · 167,665 km	$5,800
Orangeville, ON · 171,768 km	$6,495
Tecumseh, ON · 178,632 km	$2,886
Calgary, AB · 179,284 km	$11,990

§4 EVENTS

2014	Model year 2014[1] Assembly plant San Luis Potosi, Guanajuato, Mexico
23 Jan 2014	Transport Canada recall 2014019[2] Issued for the model year · Fuel system

7 Apr 2014	Transport Canada recall 2014115[2] Issued for the model year · Brakes
3 Jul 2014	Transport Canada recall 2014274[2] Issued for the model year · Accessories
29 Jul 2014	Transport Canada recall 2014315[2] Issued for the model year · Seats and restraints
28 Apr 2016	Transport Canada recall 2016191[2] Issued for the model year · Electrical
9 Sep 2016	Transport Canada recall 2016439[2] Issued for the model year · Airbag
28 Oct 2026	Listed for sale, Ottawa, ON[5] JANEX AUTO SALES · asking $6,999
29 Oct 2026	Listing last updated[5] asking $6,999

§5 DOCUMENTS

Window sticker — This VIN reads as model year 1984 or 2014, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 22 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.