Register entry, as of 23 November 2026 Listed for sale Record ID e4b2c0694a54

2013 Chevrolet Trax 1LT

1.4 L, 4 cylinders · FWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3GN	CJLSB	9	D	L	214592
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Trax · 1.4 L	Verified	2013	San Luis Potosi	Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	1.4 L, 4 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Trax	Drive	FWD
Trim	1LT	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	San Luis Potosi, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/trax/2013

6 recalls listed by Transport Canada for this model year

Airbag

2023412 27 Jul 2023

Issue: On certain vehicles, the driver-front airbag inflator could rupture when the airbag deploys in a crash. If this happens, the airbag may not properly inflate and fragments could be propelled toward vehicle occupants. Safety Risk: An airbag inflator that ruptures can create a risk of injury or death. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-front airbag module.

Electrical

2016191 28 Apr 2016

Certain vehicles equipped with a "Bring Your Own Media" (BYOM) radio may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 114 - Theft Protection and Rollaway Protection. The radio software may fail to provide an audible warning/reminder chime that meets the requirements of the standard if the ignition key is left in the off position and the driver delays opening the driver's door for more than 10 minutes, or opens and closes the door several times. The loss of an audible warning when a key is left in the ignition may increase the risk of vehicle theft. Correction: Dealers will reprogram the radio with corrected operating software.

Seats and restraints

2014343 11 Aug 2014

On certain vehicles, the front outboard driver and passenger seatbelt pretensioners may not function as designed in the event of a crash. The pretensioners could retract upon deployment but fail to lock in the retracted position, allowing the seat belt to return to the original position. This could increase the risk of injury in a crash that warrants seatbelt pretensioner deployment. Correction: Dealers will replace affected pretensioners.

Seats and restraints

2014315 29 Jul 2014

On certain vehicles, the hook bracket assembly for either front seat may have been manufactured with an incomplete weld. If the weld is incomplete and the assembly is exposed to a high load condition, the hook may separate from the seat track. This could increase the risk of occupant injury during a crash. Correction: Dealers will inspect the weld, and if necessary, replace the lower seat track.

Accessories

2014274 3 Jul 2014

On certain vehicles, insulation on the engine block heater power cord may become damaged if the cord is handled during very cold days (temperatures below -25C). This could create an electrical shock hazard, which could result in personal injury. Correction: Dealers will replace the block heater cord.

Brakes

2014115 7 Apr 2014

On certain vehicles, the left front brake line may have been routed incorrectly and may come into contact with the transmission cooler outlet pipe, causing abrasion damage which could result in a brake fluid leak. This could increase stopping distances, possibly resulting in a crash causing property damage and/or personal injury. Correction: Dealers will inspect and reroute and/or replace the brake line, as necessary.

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $6,590[5], the median[4].



Lowest ask	$3,850
Middle half	$6,495 – $8,995
Median ask	$6,590
This car	$6,590

Same model year · 5 live listings · as of 23 Nov 2026

OTHER 2013 CHEVROLET TRAX LISTINGS [5]

Stratford, ON · 300,158 km	$3,850
London, ON · 169,565 km	$6,495
Calgary, AB · 112,121 km	$8,995
Oshawa, ON · 112,089 km	$7,795
Alma, QC · 109,100 km	$9,995

§4 EVENTS

2013	Model year 2013[1] Assembly plant San Luis Potosi, Mexico
7 Apr 2014	Transport Canada recall 2014115[2] Issued for the model year · Brakes
3 Jul 2014	Transport Canada recall 2014274[2] Issued for the model year · Accessories

29 Jul 2014	Transport Canada recall 2014315[2]	Issued for the model year · Seats and restraints
11 Aug 2014	Transport Canada recall 2014343[2]	Issued for the model year · Seats and restraints
28 Apr 2016	Transport Canada recall 2016191[2]	Issued for the model year · Electrical
27 Jul 2023	Transport Canada recall 2023412[2]	Issued for the model year · Airbag
19 Nov 2026	Listed for sale, St-Basile-Le-Grand, QC[5]	Olivier Hyundai St-Basile · asking $6,590
22 Nov 2026	Listing last updated[5]	asking $6,590

§5 DOCUMENTS

Window sticker	This VIN reads as model year 1983 or 2013, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 5 live listings, as of 23 Nov 2026
[5] Live public dealer listings on Cardog, as of 23 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.