Register entry, as of 29 October 2026 Listed for sale Record ID 948671bf2701

2015 Cadillac SRX Luxury

3.6 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3GY	FNEE3	1	F	S	588997
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Cadillac · GENERAL MOTO…	SRX · 3.6 L	Verified	2015	Ramos Arizpe	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	3.6 L, 6 cylinders
Make	Cadillac	Fuel	Gasoline
Model	SRX	Drive	AWD
Trim	Luxury	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Ramos Arizpe, Coahuila, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/cadillac/srx/2015

4 recalls listed by Transport Canada for this model year

Airbag

2026246 21 May 2026

Issue: On certain vehicles, the driver-front airbag inflator could rupture when the airbag deploys in a crash. If this happens, the airbag may not properly inflate and metal fragments could be propelled toward vehicle occupants. Safety Risk: An airbag inflator that ruptures can create a risk of injury or death. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-front airbag module.

Suspension

2021394 24 Jun 2021

Issue: On certain vehicles, the adjustable rear toe link may not have been properly tightened during a previous service repair. As a result, the toe link could loosen and eventually separate. This could cause a sudden loss of vehicle stability. Note: You may notice the following warning symptoms if a rear toe link is loose: - sway or wander while driving; - loud metallic or other unusual noise from the rear suspension; - the steering wheel may be off-center; - the Stabilitrak malfunction indicator lamp (MIL) may stay on or flash while driving; - Uneven wear between the rear tires. If you detect these symptoms, you should stop driving and have the vehicle towed to the nearest dealership. Safety Risk: A loss of stability could increase the risk of a crash. Corrective Action: General Motors will notify owners by mail and instruct you to take your vehicle to a dealer to replace the adjustable rear toe links with a newly designed part.

Seats and restraints

2014572 17 Dec 2014

On certain vehicles, the driver's front seat may have been assembled with an incorrect seat track bracket. Driver seats with this condition may not be properly attached to the seat track, which could result in an audible buzz or rattle. In the event of a severe rear collision, a portion of the driver seat – i.e., the front outboard seat bracket – may disengage from the seat track, potentially increasing the risk of injury. Correction: Dealers will inspect, and if required, replace the drivers outboard front seat track hook bracket.

Suspension

2014406 18 Sep 2014

On certain vehicles, the rear suspension toe link jam nuts may not have been tightened to specification. If the vehicle is operated in this condition, the toe link nuts could loosen and eventually separate, allowing the rear wheel to turn inboard or outboard. If this were to happen, sudden changes in vehicle handling could occur, which could result in a crash causing injury and/or property damage. Correction: Dealers will inspect and ensure the rear suspension toe link nuts are tightened to specification. If required, the rear suspension toe link will be replaced.

> Listed for the model year, not checked against your VIN. Cadillac confirms which apply.
> Check your VIN with Cadillac Canada or call a Cadillac dealer with your VIN.
> www.cadillaccanada.ca/en/ownercenter/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $15,980[5], $4,481 over the median of $11,499[4].



Lowest ask	$4,500
Middle half	$10,924 – $13,990
Median ask	$11,499
This car	$15,980

Same model year · 9 live listings · as of 29 Oct 2026

OTHER 2015 CADILLAC SRX LISTINGS [5]

Brantford, ON · 192,465 km	$10,924
Winnipeg, MB · 185,610 km	$9,900
Barrie, ON · 159,909 km	$13,990
Brandon, MB · 76,359 km	$15,900
Cobourg, ON · 162,119 km	$11,499
Toronto, ON · 110,426 km	$11,995

§4 EVENTS

2015	Model year 2015[1] Assembly plant Ramos Arizpe, Coahuila, Mexico
18 Sep 2014	Transport Canada recall 2014406[2] Issued for the model year · Suspension
17 Dec 2014	Transport Canada recall 2014572[2] Issued for the model year · Seats and restraints
24 Jun 2021	Transport Canada recall 2021394[2] Issued for the model year · Suspension
24 Nov 2025	Listed for sale, Oakville, ON[5] Medallion Motors Inc · asking $15,980

21 May 2026	Transport Canada recall 2026246[2] Issued for the model year · Airbag
29 Oct 2026	Listing last updated[5] asking $15,980

§5 DOCUMENTS

Window sticker — This VIN reads as model year 1985 or 2015, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 9 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.