

Register entry, as of 29 October 2026

Listed for sale

Record ID 4ec36719af3c

2019 Honda Fit LX SENSING

1.5 L, 4 cylinders · 4x2 · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3HG **GK5H5** **5** **K** **M** **103907**

WMI 1-3

Honda De Mexico, S.A. De...

DESCRIPTOR 4-8

Fit · 1.5 L

CHECK 9

Verified

YEAR 10

2019

PLANT 11

Celaya

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	1.5 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	Fit	Drive	4x2
Trim	LX SENSING	Maker	HONDA DE MEXICO, S.A. DE C.V.
Body	Hatchback	Plant	Celaya, Guanajuato, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/fit/2019

6 recalls listed by Transport Canada for this model year

Visual system

2024305 30 May 2024

Issue: Under certain conditions, the battery voltage could drop when starting the engine. If this happens, the display audio system may not start. As a result, the rearview image will not appear on the display screen when reversing. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall replaces Transport Canada recall no. 2023-041. The software update completed by a Honda dealer during recalls HP35 and HP36 (Transport Canada recall no. 2023-041) may not have been effective. As a result, a second repair is required. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to update the display audio software.

Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.



Visual system

2023041 2 Feb 2023

Issue: Under certain conditions, the battery voltage could drop when starting the engine. If this happens, the display audio system may not start. As a result, the rearview image will not appear on the display screen when reversing. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealership to update the display audio software.

Fuel system

2021182 26 Mar 2021

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada Recall No. 2020-236. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump motor.

Fuel system

2020236 28 May 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: For the RLX model, only the RLX Hybrid model is affected by this recall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump motor.

Listed for the model year, not checked against your VIN. Honda confirms which apply.

Check your VIN with Honda Canada or call a Honda dealer with your VIN.

www.honda.ca/en/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$17,900^[5], \$341 under the median of \$18,241^[4].



Lowest ask	\$11,682
Middle half	\$17,888 – \$24,255
Median ask	\$18,241
This car	\$17,900

Same model year · 12 live listings · as of 29 Oct 2026

OTHER 2019 HONDA FIT LISTINGS ^[5]

Stratford, ON · 36,722 km	\$24,820
Milton, ON · 32,605 km	\$24,999
Ottawa, ON · 77,902 km	\$17,888
Scarborough, ON · 49,268 km	\$24,688
St. Catharines, ON · 37,886 km	\$24,111
Milton, ON · 32,605 km	\$24,999

§4 EVENTS

2019

Model year 2019^[1]

Assembly plant Celaya, Guanajuato, Mexico



28 May 2020	Transport Canada recall 2020236 ^[2] Issued for the model year · Fuel system
26 Mar 2021	Transport Canada recall 2021182 ^[2] Issued for the model year · Fuel system
2 Feb 2023	Transport Canada recall 2023041 ^[2] Issued for the model year · Visual system
18 Dec 2023	Transport Canada recall 2023679 ^[2] Issued for the model year · Fuel system
6 May 2024	Transport Canada recall 2024262 ^[2] Issued for the model year · Fuel system
30 May 2024	Transport Canada recall 2024305 ^[2] Issued for the model year · Visual system
26 Oct 2026	Listed for sale, Sherbrooke, QC ^[5] Les Inventaires MT Inc. · asking \$17,900
29 Oct 2026	Listing last updated ^[5] asking \$17,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 12 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

