Register entry, as of 5 November 2026 Listed for sale Record ID 76e3f9371c78

# 2019 Hyundai Accent SE and SEL

1.6 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3KP | C25A3 | X | K | E | 081161 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Hyundai · KIA MEXICO S.A.... | Accent · 1.6 L | Verified | 2019 | Tijuana | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2019 | Engine | 1.6 L, 4 cylinders |
| Make | Hyundai | Fuel | Gasoline |
| Model | Accent | Drive | Not in the decode |
| Trim | SE and SEL | Maker | KIA MEXICO S.A. DE C.V. |
| Body | Hatchback | Plant | Tijuana, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/hyundai/accent/2019

**2** recalls listed by Transport Canada for this model year

### Structure

2021495 6 Aug 2021

Issue: On certain vehicles, a part in the trunk release latch could fail. If this happens, the emergency trunk release located inside the trunk compartment may not work properly. This could prevent a person that is trapped inside the trunk from opening it. Note: For the 2016 model year Sonata, only the Sonata Hybrid is affected by this recall. Safety Risk: If a person is closed inside the trunk compartment, they may not be able to get out. This could create a risk of injury. Corrective Actions: Hyundai will notify owners by mail and instruct you to take your vehicle to a dealer to replace the trunk latch assembly.

### Heater and defroster

2019142 18 Mar 2019


Issue: On certain 5-door cars, when the rear defroster is switched on, the rear glass may develop hot spots. Safety Risk: A person that comes in contact with hot spots on the rear glass could have an increased risk of a burn injury. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their car to a dealer to have the rear glass replaced.

> Listed for the model year, not checked against your VIN. Hyundai confirms which apply.
> Check your VIN with Hyundai Canada or call a Hyundai dealer with your VIN.
> www.hyundaicanada.com/en/owners-section/recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $10,999[5], $2,500 under the median of $13,499[4].




| | |
|---|---|
| Lowest ask | $8,499 |
| Middle half | $10,999 – $13,995 |
| Median ask | $13,499 |
| This car | $10,999 |

Same configuration · 21 live listings · as of 5 Nov 2026

### OTHER 2019 HYUNDAI ACCENT LISTINGS [5]

| | |
|---|---|
| Gatineau, QC · 32,240 km | $16,495 |
| Lasalle, QC · 126,359 km | $11,495 |
| Gatineau, QC · 32,240 km | $16,495 |
| Carignan, QC · 108,894 km | $13,498 |
| Gatineau, QC · 32,240 km | $16,495 |
| Chambly, QC · 95,436 km | $12,999 |

## §4 EVENTS

| | |
|---|---|
| 2019 | Model year 2019[1]<br>Assembly plant Tijuana, Mexico |
| 18 Mar 2019 | Transport Canada recall 2019142[2]<br>Issued for the model year · Heater and defroster |
| 6 Aug 2021 | Transport Canada recall 2021495[2]<br>Issued for the model year · Structure |
| 4 Nov 2026 | Listed for sale, Ottawa, ON[5]<br>Envoy Auto Sales · asking $10,999 |
| 5 Nov 2026 | Listing last updated[5]<br>asking $10,999 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 21 live listings, as of 5 Nov 2026
[5] Live public dealer listings on Cardog, as of 5 Nov 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.