Register entry, as of 29 October 2026 Listed for sale Record ID c2be349f32c9

2020 Mazda CX-30 Preferred Pkg

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3MV	DMBDM	6	L	M	137197
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mazda Motor Manufacturin…	CX-30 · 2.5 L	Verified	2020	Salamanca	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	2.5 L, 4 cylinders
Make	Mazda	Fuel	Gasoline
Model	CX-30	Drive	4WD
Trim	Preferred Pkg	Maker	MAZDA MOTOR MANUFACTURING DE MEXICO S.A. DE C.V.
Body	Sport Utility Vehicle	Plant	Salamanca, Guanajuato, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mazda/cx-30/2020

3 recalls listed by Transport Canada for this model year

Structure

2021075 19 Feb 2021

Issue: On certain vehicles, the power liftgate may partially lower from the fully open position when the vehicle is parked facing uphill on a slope. The liftgate will not lower all the way to the closed position. Safety risk: A liftgate that partially lowers suddenly could create a risk of injury. Corrective action: Mazda will notify owners by mail and instruct you to take your vehicle to a dealer to update the power liftgate software. The dealer will also inspect the liftgate drive units and replace them, if necessary.

Fuel system

2020265 12 Jun 2020

Issue: On certain vehicles equipped with all-wheel drive, a hose that connects the evaporative emissions (EVAP) system to the fuel tank may not have been installed correctly. This could cause fuel to flow directly into the EVAP system when the fuel tank is filled completely. As a result, fuel may leak through the charcoal canister vent. A charcoal canister that is filled with fuel could also cause the engine to stall. Note: This problem could cause the malfunction indicator light (MIL) to turn on in the instrument cluster and/or the active driving display. Safety Risk: A fuel leak can create the risk of a fire. An engine that stalls while driving could increase the risk of a crash. Corrective Actions: Mazda will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the EVAP hose connection inside the fuel tank and reconnect it, if necessary. If the hose is found disconnected, the charcoal canister will also be replaced. You should avoid completely filling the fuel tank until the recall repairs are completed.

Brakes

2020264 12 Jun 2020

Issue: On certain vehicles, the front brake caliper mounting bolts may not be properly tightened. This could cause the bolts to loosen, which may result in reduced brake effectiveness. If the bolts fall out, the caliper could also come in contact with the wheel rim and cause a loss of vehicle control. Safety Risk: Reduced brake effectiveness could cause an increase in stopping distance and create the risk of a crash. A loss of vehicle control could increase the risk of a crash. Corrective Actions: Mazda will notify owners by mail and instruct you to take your vehicle to a dealer to check the tightening torque of the front brake caliper mounting bolts. If a bolt is missing, the caliper and remaining bolt will be replaced.

> Listed for the model year, not checked against your VIN. Mazda confirms which apply.
> Check your VIN with Mazda Canada or call a Mazda dealer with your VIN.
> www.mazdarecalls.ca/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $20,789[5], $2,006 under the median of $22,795[4].



Lowest ask	$16,999
Middle half	$20,920 – $24,036
Median ask	$22,795
This car	$20,789

Same model year · 19 live listings · as of 29 Oct 2026

OTHER 2020 MAZDA CX-30 LISTINGS [5]

London, ON · 33,592 km	$23,695
Kentville, NS · 125,074 km	$20,500
Québec, QC · 34,775 km	$23,499
Notre-Dame-Des-Prairies, QC · 80,934 km	$21,495
Yarmouth, NS · 125,074 km	$20,500
Waterloo, ON · 94,000 km	$22,995

§4 EVENTS

2020	Model year 2020[1] Assembly plant Salamanca, Guanajuato, Mexico
12 Jun 2020	Transport Canada recall 2020265[2] Issued for the model year · Fuel system
12 Jun 2020	Transport Canada recall 2020264[2] Issued for the model year · Brakes
19 Feb 2021	Transport Canada recall 2021075[2] Issued for the model year · Structure
27 Oct 2026	Listed for sale, Barrie, ON[5] Jackson's Toyota · asking $20,789

28 Oct 2026	Listing last updated[5] asking $20,789

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 19 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.