Register entry, as of 29 November 2026 Listed for sale Record ID 2fecec660252

2016 Mazda Mazda3 Touring/GS

2.0 L, 4 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3MZ	BM1L7	1	G	M	316183
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Mazda Motor Manufacturin…	Mazda3 · 2.0 L	Verified	2016	Guanajuato	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	2.0 L, 4 cylinders
Make	Mazda	Fuel	Gasoline
Model	Mazda3	Drive	Not in the decode
Trim	Touring/GS	Maker	MAZDA MOTOR MANUFACTURING DE MEXICO S.A. DE C.V.
Body	Hatchback	Plant	Guanajuato, Salamanca, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mazda/mazda3/2016

6 recalls listed by Transport Canada for this model year

Visual system

2023391 14 Jul 2023

Issue: On certain vehicles, a problem with the rearview camera connector could cause distortion or flickering of the rearview camera image. Note: This recall only affects hatchback (5-door) models. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mazda will notify owners by mail and advise you to take your vehicle to a dealership to inspect the rearview camera and install a seal for the wiring harness. The dealer will replace the rearview camera, if necessary.

Visual system

2019169 4 Apr 2019

Issue: An electrical problem may cause the windshield wipers to stop working. Safety Risk: Windshield wipers that do not work could affect a driver’s visibility under certain conditions. This could increase the risk of a crash. Corrective Actions: Mazda will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front body control module with an improved one.

Brakes

2017312 22 Jun 2017

On certain vehicles equipped with hand-operated parking brakes, the rear brake caliper protective boot on the parking brake system may not perform as intended, causing the parking brake actuator shaft to corrode. Over time, the actuator shaft may become stuck in the brake caliper body which could lead to decreased parking brake holding force or cause the parking brake to drag while driving. Decreased parking brake holding force could cause the vehicle to roll away if parked on a slope which would increase the risk of injury and/or damage to property. Correction: Dealers will inspect and repair or replace the rear caliper assemblies as necessary.

Fuel system

2016465 22 Sep 2016

On certain vehicles. the fuel tank may contain a defect which could allow a weld to break, potentially resulting in a fuel leak. A fuel leak in the presence of an ignition source could result in a fire causing injury and/or property damage. Correction: Dealers will inspect the fuel tank and replace if necessary.

Fuel system

2016464 22 Sep 2016

On certain vehicles. the fuel tank may contain a defect which could allow a weld to break, potentially resulting in a fuel leak. A fuel leak in the presence of an ignition source could result in a fire causing injury and/or property damage. Correction: Dealers will inspect the fuel tank and replace if necessary.

Fuel system

2015444 2 Oct 2015

Certain vehicles may have been manufactured with defective fuel tank shut-off-valves. Under certain conditions, this could cause fuel to flow through the shut-off-valve into the charcoal canister and leak from the external vent. Fuel leakage, in the presence of an ignition source, could result in a fire causing injury and/or property damage. Correction: Dealers will inspect and replace the charcoal canister and associated fuel tank components.

> Listed for the model year, not checked against your VIN. Mazda confirms which apply.
> Check your VIN with Mazda Canada or call a Mazda dealer with your VIN.
> www.mazdarecalls.ca/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $10,488[5], $2,212 under the median of $12,700[4].



Lowest ask	$5,700
Middle half	$8,671 – $14,624
Median ask	$12,700
This car	$10,488

Same configuration · 12 live listings · as of 29 Nov 2026

OTHER 2016 MAZDA MAZDA3 LISTINGS [5]

Montréal, QC · 151,644 km	$8,989
Toronto, ON · 98,483 km	$10,999
Scarborough, ON · 229,836 km	$7,970
Calgary, AB · 124,861 km	$12,998
Laval, QC · 19,306 km	$15,950
Laval, QC · 146,000 km	$6,499

§4 EVENTS

2016	Model year 2016[1] Assembly plant Guanajuato, Salamanca, Mexico
2 Oct 2015	Transport Canada recall 2015444[2] Issued for the model year · Fuel system

22 Sep 2016	Transport Canada recall 2016465[2]	Issued for the model year · Fuel system
22 Sep 2016	Transport Canada recall 2016464[2]	Issued for the model year · Fuel system
22 Jun 2017	Transport Canada recall 2017312[2]	Issued for the model year · Brakes
4 Apr 2019	Transport Canada recall 2019169[2]	Issued for the model year · Visual system
14 Jul 2023	Transport Canada recall 2023391[2]	Issued for the model year · Visual system
9 Sep 2026	Listed for sale, Brossard, QC[5]	Park Avenue Honda · asking $10,488
29 Nov 2026	Listing last updated[5]	asking $10,488

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 12 live listings, as of 29 Nov 2026

[5] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.