Register entry, as of 28 October 2026 Listed for sale Record ID c96b227e1c06

2021 Nissan Sentra SR

2.0 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3N1	AB8DV	4	M	Y	214393
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Nissan Mexicana, S.A. De C...	Sentra · 2.0 L	Verified	2021	Aguascalientes	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.0 L, 4 cylinders
Make	Nissan	Fuel	Gasoline
Model	Sentra	Drive	4x2
Trim	SR	Maker	NISSAN MEXICANA, S.A. DE C.V.
Body	Sedan	Plant	Aguascalientes, Aguascalientes, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/sentra/2021

3 recalls listed by Transport Canada for this model year

Visual system

2023504 11 Sep 2023

Issue: On certain vehicles, the rearview camera wiring harness could be damaged by movement and vibrations. If this happens, the rearview camera image may not display correctly or may not display at all. Canadian regulations require the rearview image to display when reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Nissan will notify owners by mail and advise you to bring your vehicle to a dealership to inspect the rearview camera wiring harness, apply a protective tape, and reroute it. If the wiring is damaged, the rearview camera and wiring harness will be replaced.

Steering

2023462 16 Aug 2023

Issue: On certain vehicles, the left and/or right tie rod(s) may not be strong enough. Under certain conditions (like hitting a curb or a large pothole), the tie rod(s) could bend and/or break and cause a partial loss of steering control. Safety Risk: A loss of steering control could create the risk of a crash. Corrective Actions: Nissan will notify owners by mail. Due to a parts supply issue, Nissan will advise you to take your vehicle to the dealership only if you experience a vibration in the steering wheel or if the steering wheel is off-center. When enough parts are available, Nissan will re-notify owners and instruct you to take your vehicle to a dealership to replace the left and right tie rods.

Steering

2021382 18 Jun 2021

Issue: On certain vehicles, one or both of the front tie rods may have be bent during vehicle production. This could cause the steering wheel to be off center and/or cause a vibration while driving. There is also a risk that the tie rod could break, which can cause a partial loss of steering control. Safety Risk: A loss of steering control could create the risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your car to a dealer inspect the left and right-front tie rods. If a tie rod is bent, it will be replaced.

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $20,995[5], $3,095 over the median of $17,900[4].



Lowest ask	$13,999
Middle half	$16,373 – $19,914
Median ask	$17,900
This car	$20,995

Same configuration · 24 live listings · as of 28 Oct 2026

OTHER 2021 NISSAN SENTRA LISTINGS [5]

Ajax, ON · 109,972 km	$15,999
Whitby, ON · 103,386 km	$14,500
Gatineau, QC · 77,881 km	$14,995
Edmonton, AB · 80,299 km	$15,888
Barrie, ON · 125,080 km	$16,865
Saint-Basile-Le-Grand, QC · 64,030 km	$15,486

§4 EVENTS

2021	Model year 2021[1] Assembly plant Aguascalientes, Aguascalientes, Mexico
18 Jun 2021	Transport Canada recall 2021382[2] Issued for the model year · Steering
16 Aug 2023	Transport Canada recall 2023462[2] Issued for the model year · Steering
11 Sep 2023	Transport Canada recall 2023504[2] Issued for the model year · Visual system
19 Apr 2026	Listed for sale, Sudbury, ON[5] The Car Lot · asking $20,995
28 Oct 2026	Listing last updated[5] asking $20,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 24 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.