Register entry, as of 27 October 2026 Listed for sale Record ID 3b04223a1d24

2007 Nissan Versa

1.8 L, 4 cylinders · 4x2 · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3N1	BC13E	0	7	L	370183
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Nissan Mexicana, S.A. De C...	Versa · 1.8 L	Verified	2007	Aguascalientes City	Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	1.8 L, 4 cylinders
Make	Nissan	Fuel	Gasoline
Model	Versa	Drive	4x2
Trim	Not in the decode	Maker	NISSAN MEXICANA, S.A. DE C.V.
Body	Hatchback	Plant	Aguascalientes City, Aguascalientes, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/versa/2007

7 recalls listed by Transport Canada for this model year

Airbag

2017356 18 Jul 2017

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the driver frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the driver frontal airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected. Additional Note: This campaign affects 2007-2012 Versa hatchback models and 2007-2011 Versa sedan models. The 2012 model year Nissan Versa sedan is not involved.

Airbag

2017023 12 Jan 2017

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

Suspension

2015402 14 Sep 2015

On certain vehicles, the front suspension coil springs may have been manufactured with an inadequate phosphorous coating, and/or could have low residual stress in the springs. This inadequate coating could lead to cracking due to coil-to-coil contact when the spring is compressed, which would allow the spring to be more susceptible to corrosion. In some instances coil spring breakage could occur. If ignored, broken front coil spring could damage the front tires and cause rapid air loss and/or tire failure, which could affect the driver's ability to bring the vehicle to a controlled stop, increasing the risk of a crash causing injury and/or property damage. Correction: Dealers will replace both front coil springs.

Lights and instruments

2010434 7 Dec 2010

On certain vehicles, the relays in the daytime running light (DRL) circuit could have become contaminated with silicon during the assembly process. This could, in some circumstances, cause one or both of the relays to stop functioning, which would cause one or both of the daytime running lights not to illuminate automatically when the vehicle is driven. Should this condition occur, the lack of DRL function may render the vehicle less visible to other motorists and pedestrians, possibly resulting in a vehicle crash. Correction: Dealers will replace the relays for the daytime running lights circuit.

Airbag

2007069 9 Mar 2007

On certain vehicles, the terminals for the passenger side seatbelt tension sensor harness connector may have been damaged during manufacturing process. This could result in a loss of electrical continuity causing the Occupant Detection System to become inoperative. If this occurs, the airbag warning light will come on and the passenger side frontal airbag will not deploy in a crash. Correction: Dealers will replace the connector for the seatbelt tension sensor harness.

Brakes

2006213 7 Sep 2006

Certain vehicles fail to comply with the requirements of CMVSS 135. Specifically, the "WARNING: Clean filler cap before removing" portion of the required statement on the brake fluid reservoir cap was omitted. Correction: Updated brake fluid reservoir caps will be mailed to vehicle owners along with installation instructions.

1 more on the model-year record, cardog.app/tools/recalls/nissan/versa/2007

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $2,995[5], $2,170 under the median of $5,165[4].



Lowest ask	$2,995
Middle half	$3,299 – $7,625
Median ask	$5,165
This car	$2,995

Same model year · 4 live listings · as of 27 Oct 2026

OTHER 2007 NISSAN VERSA LISTINGS [5]

Victoria, BC · 155,695 km	$6,930
Toronto, ON · 20 km	$3,400
Laval, QC · 126,776 km	$9,710

§4 EVENTS

2007	Model year 2007[1] Assembly plant Aguascalientes City, Aguascalientes, Mexico
27 Jul 2006	Transport Canada recall 2006186[2] Issued for the model year · Powertrain
7 Sep 2006	Transport Canada recall 2006213[2] Issued for the model year · Brakes
9 Mar 2007	Transport Canada recall 2007069[2] Issued for the model year · Airbag
7 Dec 2010	Transport Canada recall 2010434[2] Issued for the model year · Lights and instruments
14 Sep 2015	Transport Canada recall 2015402[2] Issued for the model year · Suspension
12 Jan 2017	Transport Canada recall 2017023[2] Issued for the model year · Airbag
18 Jul 2017	Transport Canada recall 2017356[2] Issued for the model year · Airbag
26 Oct 2026	Listed for sale, Kelowna, BC[5] Buy Direct Truck Centre · asking $2,995
27 Oct 2026	Listing last updated[5] asking $2,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 4 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.