

Register entry, as of 28 October 2026

Listed for sale

Record ID a036d3a1bda9

2017 Nissan Micra

1.6 L, 4 cylinders · 4x2 · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3N1 **CK3CP** **3** **H** **L** **267216**

WMI 1-3

Nissan Mexicana, S.A. De C...

DESCRIPTOR 4-8

Micra · 1.6 L

CHECK 9

Verified

YEAR 10

2017

PLANT 11

Aguascalientes

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	1.6 L, 4 cylinders
Make	Nissan	Fuel	Gasoline
Model	Micra	Drive	4x2
Trim	Not in the decode	Maker	NISSAN MEXICANA, S.A. DE C.V.
Body	Hatchback	Plant	Aguascalientes, Aguascalientes, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/micra/2017

2 recalls listed by Transport Canada for this model year

Electrical 2018440 22 Aug 2018

On certain vehicles equipped with a mechanical key ignition system, a spring in the ignition switch could wear and break. This may allow the ignition key to inadvertently move from the ON position to the accessory (ACC) position while driving, causing the engine to shut off and the airbag system to lose power. The resulting loss of motive power, and change in steering and brake forces could increase the risk of a crash causing injury and/or damage to property. Additionally, in the event of a crash, this may also cause the airbags not to function. Correction: Dealers will inspect the lot number of the ignition switch, and replace it with a new one if it is affected. Note: Until the correction is performed, owners are advised to remove all objects from the ignition key ring, such as additional keys, key chains, etc.

Airbag 2017566 17 Nov 2017

On certain vehicles, a bad connection at the side airbag sensor connector could cause a momentary communication loss from the side airbag sensor to the Airbag Control Unit (ACU). This would put the system in a backup state, lowering the impact threshold required for a side airbag deployment. If a door is being closed with force while the system is in this backup state, this could cause an unintended curtain airbag, seat-mounted side airbag and seat belt pretensioner deployment in a non-warranted (non-impact) situation, which would increase the risk of injury to occupants. Correction: Dealers will install a jumper harness and replace the side airbag sensor with a new one.

Listed for the model year, not checked against your VIN. Nissan confirms which apply.


Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.

www.nissan.ca/service/vin-recall.html



§3 VALUE [3]

This car asks \$12,987^[4], \$3,992 over the median of \$8,995^[3].



Lowest ask	\$3,495
Middle half	\$7,295 – \$9,999
Median ask	\$8,995
This car	\$12,987

Same configuration · 17 live listings · as of 28 Oct 2026

OTHER 2017 NISSAN MICRA LISTINGS [4]

Candiac, QC · 116,374 km	\$6,988
Vaudreuil-Dorion, QC · 111,164 km	\$8,988
Vaudreuil-Dorion, QC · 117,687 km	\$7,988
Vaudreuil-Dorion, QC · 82,837 km	\$8,798
Vaudreuil-Dorion, QC · 116,374 km	\$6,988
Sherbrooke, QC · 69,405 km	\$9,987

§4 EVENTS

2017	Model year 2017 ^[1] Assembly plant Aguascalientes, Aguascalientes, Mexico
17 Nov 2017	Transport Canada recall 2017566 ^[2] Issued for the model year · Airbag
22 Aug 2018	Transport Canada recall 2018440 ^[2] Issued for the model year · Electrical
27 Oct 2026	Listed for sale, Levis, QC ^[4] St-Nicolas Nissan · asking \$12,987
28 Oct 2026	Listing last updated ^[4] asking \$12,987

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [3] Cardog market quote, same configuration, 17 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 28 Oct 2026 |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

