Register entry, as of 29 October 2026 Listed for sale Record ID 3b595a1bb273

# 2012 Nissan Versa

1.6 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3N1 | CN7AP | 1 | C | L | 845856 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Nissan Mexicana, S.A. De C... | Versa · 1.6 L | Verified | 2012 | Aguascalientes City | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2012 | Engine | 1.6 L, 4 cylinders |
| Make | Nissan | Fuel | Gasoline |
| Model | Versa | Drive | 4x2 |
| Trim | Not in the decode | Maker | NISSAN MEXICANA, S.A. DE C.V. |
| Body | Sedan | Plant | Aguascalientes City, Aguascalientes, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/versa/2012

**7** recalls listed by Transport Canada for this model year

### Airbag

2018328 15 Jun 2018

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected. Additional Note: This campaign affects 2010-2012 Versa hatchback models and 2010-2011 Versa sedan models. The 2012 model year Nissan Versa sedan is not involved.

### Suspension

2017493 12 Oct 2017

On certain vehicles, the front suspension coil springs may have been manufactured with an inadequate phosphorous coating, and/or could have low residual stress in the springs. This inadequate coating could lead to cracking due to coil-to-coil contact when the spring is compressed, which would allow the spring to be more susceptible to corrosion. In some instances coil spring breakage could occur. If ignored, broken front coil spring could damage the front tires and cause rapid air loss and/or tire failure, which could affect the driver's ability to bring the vehicle to a controlled stop, increasing the risk of a crash causing injury and/or property damage. Correction: Dealers will replace both front coil springs. Note: This is an expansion of recall 2015-402.

### Airbag

2017356 18 Jul 2017

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the driver frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the driver frontal airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected. Additional Note: This campaign affects 2007-2012 Versa hatchback models and 2007-2011 Versa sedan models. The 2012 model year Nissan Versa sedan is not involved.

### Airbag

2017116 7 Mar 2017

On certain vehicles, a bad connection at the side airbag sensor connector could cause a momentary communication loss from the side airbag sensor to the Airbag Control Unit (ACU). This would put the system in a backup state, lowering the impact threshold required for a side airbag deployment. If a door is being closed with force while the system is in this backup state, this could cause an unintended side airbag deployment in a non-warranted (non-impact) situation, which would increase the risk of injury to occupants. Correction: Dealers will install a jumper harness and replace the side airbag sensor with a new one.

### Suspension

2015402 14 Sep 2015

On certain vehicles, the front suspension coil springs may have been manufactured with an inadequate phosphorous coating, and/or could have low residual stress in the springs. This inadequate coating could lead to cracking due to coil-to-coil contact when the spring is compressed, which would allow the spring to be more susceptible to corrosion. In some instances coil spring breakage could occur. If ignored, broken front coil spring could damage the front tires and cause rapid air loss and/or tire failure, which could affect the driver's ability to bring the vehicle to a controlled stop, increasing the risk of a crash causing injury and/or property damage. Correction: Dealers will replace both front coil springs.

### Powertrain

2015366 12 Aug 2015

On certain vehicles, the driver's foot could contact the edge of the center console lower trim panel, which could impede smooth accelerator pedal operation. The panel edge could also catch the driver's shoe, potentially resulting in a delay in the driver being able to shift their foot from the accelerator to the brake pedal. This could increase stopping distances, potentially resulting in a crash causing injury and/or damage to property. Correction: Dealers will modify the lower trim panel.

1 more on the model-year record, cardog.app/tools/recalls/nissan/versa/2012

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $4,995[5], the median[4].

| | |
|---|---|
| Lowest ask | $3,444 |
| Middle half | $3,795 – $5,995 |
| Median ask | $4,995 |
| This car | $4,995 |

Same model year · 5 live listings · as of 29 Oct 2026

### OTHER 2012 NISSAN VERSA LISTINGS [5]

| | |
|---|---|
| Sainte-Rose, QC · 94,084 km | $3,795 |
| Belleville, ON · 155,476 km | $5,995 |
| Laval, QC · 187,245 km | $3,444 |

Mississauga, ON · 168,842 km $5,995

## §4 EVENTS

| | |
|---|---|
| 2012 | Model year 2012[1]<br>Assembly plant Aguascalientes City, Aguascalientes, Mexico |
| 1 Feb 2012 | Transport Canada recall 2012034[2]<br>Issued for the model year · Powertrain |
| 12 Aug 2015 | Transport Canada recall 2015366[2]<br>Issued for the model year · Powertrain |
| 14 Sep 2015 | Transport Canada recall 2015402[2]<br>Issued for the model year · Suspension |
| 7 Mar 2017 | Transport Canada recall 2017116[2]<br>Issued for the model year · Airbag |
| 18 Jul 2017 | Transport Canada recall 2017356[2]<br>Issued for the model year · Airbag |
| 12 Oct 2017 | Transport Canada recall 2017493[2]<br>Issued for the model year · Suspension |
| 15 Jun 2018 | Transport Canada recall 2018328[2]<br>Issued for the model year · Airbag |
| 25 Oct 2026 | Listed for sale, London, ON[5]<br>Tiger Auto Sales Ltd. · asking $4,995 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $4,995 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 5 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.