Register entry, as of 23 November 2026 Listed for sale Record ID 4e5449f7d1ef

2021 Nissan Kicks S

1.6 L, 4 cylinders · 4x2 · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3N1	CP5BV	9	M	L	509787
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Nissan Mexicana, S.A. De C…	Kicks · 1.6 L	Verified	2021	Aguascalientes	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	1.6 L, 4 cylinders
Make	Nissan	Fuel	Gasoline
Model	Kicks	Drive	4x2
Trim	S	Maker	NISSAN MEXICANA, S.A. DE C.V.
Body	Hatchback	Plant	Aguascalientes, Aguascalientes, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/kicks/2021

2 recalls listed by Transport Canada for this model year

Steering — 2023428 — 3 Aug 2023

Issue: On certain vehicles, a problem with the torque sensor in the electric power steering (EPS) system could cause a loss of power steering assist. Note: Vehicles that were inspected under Transport Canada recall 2022-527 also require this inspection. Vehicles that had the steering column replaced are not affected by this recall. Safety Risk: A loss of power steering assist can cause a sudden increase in steering effort and create the risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the lot code on the steering column torque sensor. The steering column assembly will be replaced, as needed.

Steering — 2022527 — 16 Sep 2022

Issue: On certain vehicles, a problem with the torque sensor in the electric power steering system (EPS) could cause a loss of power steering assist. Safety Risk: A loss of power steering assist can cause a sudden increase in steering effort and create the risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the lot code on the steering column torque sensor. The steering column assembly will be replaced, as needed.

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $18,999[5], $3,005 over the median of $15,994[4].



Lowest ask	$10,899
Middle half	$14,794 – $16,995
Median ask	$15,994
This car	$18,999

Same configuration · 39 live listings · as of 23 Nov 2026

OTHER 2021 NISSAN KICKS LISTINGS [5]

Middleton, NS · 131,562 km	$14,995
St-Hyacinthe, QC · 67,847 km	$15,995
Dorval, QC · 54,000 km	$15,990
Nepean, ON · 48,131 km	$18,696
Victoria, BC · 58,015 km	$18,595
Brossard, QC · 119,274 km	$13,998

§4 EVENTS

2021	Model year 2021[1] Assembly plant Aguascalientes, Aguascalientes, Mexico
16 Sep 2022	Transport Canada recall 2022527[2] Issued for the model year · Steering
3 Aug 2023	Transport Canada recall 2023428[2] Issued for the model year · Steering
31 Oct 2026	Listed for sale, Edson, AB[5] Bannister Ford Edson · asking $18,999
22 Nov 2026	Listing last updated[5] asking $18,999

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 39 live listings, as of 23 Nov 2026
[5] Live public dealer listings on Cardog, as of 23 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.