Register entry, as of 27 October 2026 Listed for sale Record ID 04df68167b03

# 2021 Nissan Kicks SV

1.6 L, 4 cylinders · 4x2 · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3N1 | CP5CV | 1 | M | L | 480459 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Nissan Mexicana, S.A. De C... | Kicks · 1.6 L | Verified | 2021 | Aguascalientes | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 1.6 L, 4 cylinders |
| Make | Nissan | Fuel | Gasoline |
| Model | Kicks | Drive | 4x2 |
| Trim | SV | Maker | NISSAN MEXICANA, S.A. DE C.V. |
| Body | Hatchback | Plant | Aguascalientes, Aguascalientes, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/kicks/2021

**2** recalls listed by Transport Canada for this model year

### Steering

2023428 3 Aug 2023

Issue: On certain vehicles, a problem with the torque sensor in the electric power steering (EPS) system could cause a loss of power steering assist. Note: Vehicles that were inspected under Transport Canada recall 2022-527 also require this inspection. Vehicles that had the steering column replaced are not affected by this recall. Safety Risk: A loss of power steering assist can cause a sudden increase in steering effort and create the risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the lot code on the steering column torque sensor. The steering column assembly will be replaced, as needed.

### Steering

2022527 16 Sep 2022

Issue: On certain vehicles, a problem with the torque sensor in the electric power steering system (EPS) could cause a loss of power steering assist. Safety Risk: A loss of power steering assist can cause a sudden increase in steering effort and create the risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the lot code on the steering column torque sensor. The steering column assembly will be replaced, as needed.

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $18,331[5], $1,016 over the median of $17,315[4].

| | |
|---|---|
| Lowest ask | $14,986 |
| Middle half | $16,496 – $18,496 |
| Median ask | $17,315 |
| This car | $18,331 |

Same configuration · 38 live listings · as of 27 Oct 2026

### OTHER 2021 NISSAN KICKS LISTINGS [5]

| | |
|---|---|
| Sherbrooke, QC · 25,835 km | $18,987 |
| Edmonton, AB · 99,025 km | $17,888 |
| Carbonear, NL · 170,395 km | $12,990 |
| Wilkie, SK · 137,237 km | $14,994 |
| Victoriaville, QC · 65,025 km | $15,995 |
| Chilliwack, BC · 69,350 km | $18,998 |

## §4 EVENTS

| | |
|---|---|
| 2021 | Model year 2021[1]<br>Assembly plant Aguascalientes, Aguascalientes, Mexico |
| 16 Sep 2022 | Transport Canada recall 2022527[2]<br>Issued for the model year · Steering |
| 3 Aug 2023 | Transport Canada recall 2023428[2]<br>Issued for the model year · Steering |
| 22 Aug 2026 | Listed for sale, Wilkie, SK[5]<br>Country Ford · asking $18,331 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $18,331 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 38 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.