Register entry, as of 28 October 2026 Listed for sale Record ID aecbb909745f

2021 Nissan Kicks SR

1.6 L, 4 cylinders · 4x2 · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3N1	CP5DV	2	M	L	532308
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Nissan Mexicana, S.A. De C...	Kicks · 1.6 L	Verified	2021	Aguascalientes	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	1.6 L, 4 cylinders
Make	Nissan	Fuel	Gasoline
Model	Kicks	Drive	4x2
Trim	SR	Maker	NISSAN MEXICANA, S.A. DE C.V.
Body	Hatchback	Plant	Aguascalientes, Aguascalientes, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/nissan/kicks/2021

2 recalls listed by Transport Canada for this model year

Steering

2023428 3 Aug 2023

Issue: On certain vehicles, a problem with the torque sensor in the electric power steering (EPS) system could cause a loss of power steering assist. Note: Vehicles that were inspected under Transport Canada recall 2022-527 also require this inspection. Vehicles that had the steering column replaced are not affected by this recall. Safety Risk: A loss of power steering assist can cause a sudden increase in steering effort and create the risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the lot code on the steering column torque sensor. The steering column assembly will be replaced, as needed.

Steering

2022527 16 Sep 2022

Issue: On certain vehicles, a problem with the torque sensor in the electric power steering system (EPS) could cause a loss of power steering assist. Safety Risk: A loss of power steering assist can cause a sudden increase in steering effort and create the risk of a crash. Corrective Actions: Nissan will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the lot code on the steering column torque sensor. The steering column assembly will be replaced, as needed.

> Listed for the model year, not checked against your VIN. Nissan confirms which apply.
> Check your VIN with Nissan Canada or call a Nissan dealer with your VIN.
> www.nissan.ca/service/vin-recall.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $18,703[5], $715 over the median of $17,988[4].

Lowest ask	$13,694
Middle half	$16,821 – $18,976
Median ask	$17,988
This car	$18,703

Same configuration · 34 live listings · as of 28 Oct 2026

OTHER 2021 NISSAN KICKS LISTINGS [5]

Longueuil, QC · 45,190 km	$16,400
Carignan, QC · 45,944 km	$17,995
Thornhill, ON · 40,659 km	$19,598
Victoriaville, QC · 65,025 km	$15,995
Hamilton, ON · 48,518 km	$19,488
Sherbrooke, QC · 25,835 km	$18,987

§4 EVENTS

2021	Model year 2021[1] Assembly plant Aguascalientes, Aguascalientes, Mexico
16 Sep 2022	Transport Canada recall 2022527[2] Issued for the model year · Steering
3 Aug 2023	Transport Canada recall 2023428[2] Issued for the model year · Steering
14 Oct 2026	Listed for sale, Pointe-Claire, QC[5] Spinelli Nissan · asking $18,703
27 Oct 2026	Listing last updated[5] asking $18,703

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 34 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.