Register entry, as of 29 October 2026 Listed for sale Record ID fde5374ab8bb

2023 Toyota Tacoma SR5

3.5 L, 6 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3TY	CZ5AN	6	P	T	158817
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	Tacoma · 3.5 L	Verified	2023	Apaseo El Grande	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	3.5 L, 6 cylinders
Make	Toyota	Fuel	Gasoline
Model	Tacoma	Drive	4WD
Trim	SR5	Maker	Toyota Motor Manufacturing de Guanajuato
Body	Pickup	Plant	Apaseo El Grande, Guanajuato, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tacoma/2023

5 recalls listed by Transport Canada for this model year

Airbag

2025242 6 May 2025

Issue: On certain vehicles, the steering wheel spiral cable assembly could disconnect. If this happens, the airbag (SRS) warning lamp would turn on, and the driver-front airbag wouldn't work in a crash. This may also cause the horn or other steering wheel-mounted controls not to work properly. Note: This recall replaces Transport Canada recall no. 2023-386. Vehicles that were repaired under that recall don't require this repair. Safety Risk: An airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect the production date of the spiral cable assembly, and replace it if necessary.

Airbag

2025037 29 Jan 2025

Issue: On certain vehicles, the inspection completed by a Toyota dealer during recall SRC RF2 (Transport Canada recall no. 2023-386) may not have been done correctly. As a result, a second inspection is required. On certain vehicles, the steering wheel spiral cable assembly could disconnect. If this happens, the airbag (SRS) warning lamp would turn on, and the driver-front airbag wouldn't work in a crash. This may also cause the horn or other steering wheel-mounted controls not to work properly. Safety Risk: An airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect the production date of the spiral cable assembly, and replace it if necessary.

Label

2024166 13 Mar 2024

Issue: On a small number of trucks, the information on the tire and loading information label may be incorrect. This could lead you to overload the vehicle, inflate the tires incorrectly, and/or use the wrong rims and tires. This could lead to poor handling and/or a tire failure. Safety Risk: Poor handling or a tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your truck to a dealership to inspect and, if necessary, replace the tire and loading information label.

Powertrain

2024127 27 Feb 2024

Issue: On certain trucks, the axle housing(s) may not have been manufactured properly. As a result, the axle retaining nuts could loosen and detach. If this happens, the axle shaft(s) could separate from the axle housing(s). This could cause reduced braking and/or reduced vehicle stability. Note: This problem could cause noise, vibration and/or a differential oil leak. Safety Risk: Reduced braking can cause extended stopping distances. Reduced vehicle stability could cause a loss of control. Both issues could increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your truck to a dealership to inspect the rear axle assembly and retighten the axle retaining nuts. If weld spatter is found, it will be removed. Any damaged axle components will be repaired or replaced, as necessary.

Airbag

2023386 12 Jul 2023

This recall was replaced by Transport Canada recall no. 2025-242. Issue: On certain vehicles, the steering wheel spiral cable assembly could disconnect. If this happens, the airbag (SRS) warning lamp would turn on, and the driver-front airbag wouldn't work in a crash. This may also cause the horn or other steering wheel-mounted controls not to work properly. Safety Risk: An airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect the production date of the spiral cable assembly, and replace it if necessary.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $59,995[5], $10,015 over the median of $49,980[4].



Lowest ask	$39,888
Middle half	$45,946 – $54,110
Median ask	$49,980
This car	$59,995

Same configuration · 40 live listings · as of 29 Oct 2026

OTHER 2023 TOYOTA TACOMA LISTINGS [5]

Belleville, ON · 71,823 km	$41,995
Calgary, AB · 58,586 km	$48,799
Lethbridge, AB · 142,865 km	$42,995
Brantford, ON · 60,554 km	$42,650
Ottawa, ON · 88,371 km	$43,950
Terrace, BC · 30,155 km	$47,990

§4 EVENTS

2023	Model year 2023[1] Assembly plant Apaseo El Grande, Guanajuato, Mexico
12 Jul 2023	Transport Canada recall 2023386[2] Issued for the model year · Airbag

27 Feb 2024	Transport Canada recall 2024127[2] Issued for the model year · Powertrain
13 Mar 2024	Transport Canada recall 2024166[2] Issued for the model year · Label
29 Jan 2025	Transport Canada recall 2025037[2] Issued for the model year · Airbag
6 May 2025	Transport Canada recall 2025242[2] Issued for the model year · Airbag
19 May 2026	Listed for sale, Lachute, QC[5] Toyota Lachute · asking $59,995
29 Oct 2026	Listing last updated[5] asking $59,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 40 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.