Register entry, as of 29 October 2026 Listed for sale Record ID b4c12df7d48a

# 2024 Toyota Tacoma

2.4 L, 4 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3TY | LC5LN | 0 | R | T | 000474 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Toyota Motor Manufacturi… | Tacoma · 2.4 L | Verified | 2024 | Apaseo El Grande | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2024 | Engine | 2.4 L, 4 cylinders |
| Make | Toyota | Fuel | Gasoline |
| Model | Tacoma | Drive | 4WD |
| Trim | Not in the decode | Maker | Toyota Motor Manufacturing de Guanajuato |
| Body | Pickup | Plant | Apaseo El Grande, Guanajuato, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/tacoma/2024

**4** recalls listed by Transport Canada for this model year

### Suspension

2026384 6 Aug 2026

Issue: On certain trucks, the oil reservoirs may not be properly welded to the shock absorbers. As a result, the welds could corrode and fail and cause the reservoir(s) to detach from the vehicle. Safety Risk: An oil reservoir that detaches from the vehicle could create a hazard for other road users and increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your truck to a dealership to inspect and replace the affected rear shock absorbers, as necessary.

### Visual system

2025469 11 Sep 2025

Issue: On certain vehicles, a software problem could cause the combination meter in the instrument panel not to display when the vehicle is started. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, warning lights and malfunction tell-tales. Note: This recall only affects vehicles equipped with a 12.3-inch display. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to update the combination meter software. Alternatively, certain eligible vehicles will be sent a wireless over-the-air software update, which you can install yourself. For certain vehicles, the dealer will also inspect and, if necessary, replace the combination meter.

### Brakes

2025363 7 Jul 2025

Issue: Under certain conditions, the rear brake hoses could become damaged. Over time, the brake hoses could fail and cause a brake fluid leak. If this happens, there could be reduced braking. Note: This recall only affects certain 4WD vehicles equipped with 16-inch brakes and 17-inch or 18-inch Toyota wheels. This recall replaces Transport Canada recall 2025-051. Vehicles that were repaired under that recall don't require this repair. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to replace the rear brake hoses.

### Brakes

2025051 6 Feb 2025

This recall was replaced by Transport Canada recall no. 2025-363. Issue: Under certain conditions, the rear brake hoses could become damaged. Over time, the brake hoses could fail and cause a brake fluid leak. If this happens, there could be reduced braking. Note: This recall only affects certain 4WD vehicles equipped with 16-inch brakes and 17-inch Toyota wheels. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to replace the rear brake hoses.

> Listed for the model year, not checked against your VIN. Toyota confirms which apply.
> Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
> www.toyota.ca/en/owners/recalls/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $60,488[5], $507 under the median of $60,995[4].

| | |
|---|---|
| Lowest ask | $57,495 |
| Middle half | $60,240 – $67,200 |
| Median ask | $60,995 |
| This car | $60,488 |

Same configuration · 19 live listings · as of 29 Oct 2026

OTHER 2024 TOYOTA TACOMA LISTINGS [5]

| | |
|---|---|
| Orangeville, ON · 97,245 km | $47,972 |
| Montmagny, QC · 48,459 km | $46,993 |
| Richmond Hill, ON · 0 km | $47,315 |
| Edmonton, AB · 36,519 km | $59,924 |
| Regina, SK · 36,519 km | $59,924 |
| Winnipeg, MB · 36,519 km | $59,924 |

## §4 EVENTS

| | |
|---|---|
| 2024 | Model year 2024[1]<br>Assembly plant Apaseo El Grande, Guanajuato, Mexico |
| 6 Feb 2025 | Transport Canada recall 2025051[2]<br>Issued for the model year · Brakes |
| 7 Jul 2025 | Transport Canada recall 2025363[2]<br>Issued for the model year · Brakes |
| 11 Sep 2025 | Transport Canada recall 2025469[2]<br>Issued for the model year · Visual system |
| 6 Aug 2026 | Transport Canada recall 2026384[2]<br>Issued for the model year · Suspension |

| | |
|---|---|
| 25 Oct 2026 | Listed for sale, Burnaby, BC[5]<br>Destination Toyota · asking $60,488 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $60,488 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 19 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.