Register entry, as of 17 November 2026 Listed for sale Record ID 3645da4aa7dc

2019 Volkswagen Tiguan 4Motion SE, 4Motion SEL, 4Motion SEL R-Line, 4Motion SEL R-Line Jet-Black

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VV	2B7AX	9	K	M	170169
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen De Mexico Sa…	Tiguan · 2.0 L	Verified	2019	Puebla	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Tiguan	Drive	AWD
Trim	4Motion SE, 4Motion SEL, 4Motion SEL R-Line, 4Motion SEL R-Line Jet-Black	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Sport Utility Vehicle	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/tiguan/2019

4 recalls listed by Transport Canada for this model year

Structure

2022170 6 Apr 2022

Issue: This recall is for accessory rear hatch spoilers that were installed on a new vehicle or sold as an accessory part at a Volkswagen dealership. On certain vehicles, the rear spoiler might not be properly attached to the hatch. As a result, the spoiler could detach from the vehicle while driving. Safety Risk: A spoiler that detaches from the vehicle could create a hazard for other drivers and nearby people. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to replace the rear hatch spoiler.

Label

2019158 28 Mar 2019

Issue: The compliance label may list the wrong tire size and recommended tire inflation pressures. Using a tire that is not properly inflated, or that is the wrong size, could cause a tire failure or result in poor driving performance. Safety Risk: A tire failure could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to inspect and replace the compliance label as required.

Suspension

2019116 6 Mar 2019

Issue: On certain vehicles, the rear suspension coil springs may not have been properly manufactured and could break over time. This could cause damage to a rear tire, resulting in rapid air loss and/or tire failure. Safety Risk: A rear tire failure could affect vehicle control. Additionally, a broken coil spring could also create a road hazard for other motorists. Both of these conditions may increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have both of the rear axle coil springs replaced. If a broken coil spring is found, the rear tires should be inspected for damage and replaced as required.

Lights and instruments

2018644 21 Nov 2018


Certain vehicles do not to conform to Canada Motor Vehicle Safety Standard (CMVSS) 114 - Theft Protection and Rollaway Prevention. Due to incorrect programming, the vehicle may fail to provide an audible warning when a driver opens their door after turning off the ignition, and the key is left in the ignition switch. This could increase the risk of vehicle theft. Correction: Dealers will reprogram the instrument cluster.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $12,995[5], $3,995 under the median of $16,990[4].



Lowest ask	$8,800
Middle half	$14,438 – $19,492
Median ask	$16,990
This car	$12,995

Same configuration · 35 live listings · as of 17 Nov 2026

OTHER 2019 VOLKSWAGEN TIGUAN LISTINGS [5]

Komoka, ON · 124,355 km	$15,995
North York, ON · 129,141 km	$14,880
Brossard, QC · 117,942 km	$14,992
Duncan, BC · 92,130 km	$22,818
Drummondville, QC · 124,867 km	$16,489
Abbotsford, BC · 114,579 km	$18,991

§4 EVENTS

2019	Model year 2019[1] Assembly plant Puebla, Mexico
21 Nov 2018	Transport Canada recall 2018644[2] Issued for the model year · Lights and instruments
6 Mar 2019	Transport Canada recall 2019116[2] Issued for the model year · Suspension

28 Mar 2019	Transport Canada recall 2019158[2]	Issued for the model year · Label
6 Apr 2022	Transport Canada recall 2022170[2]	Issued for the model year · Structure
15 Nov 2026	Listed for sale, Saskatoon, SK[5]	Carget Automotive · asking $12,995
16 Nov 2026	Listing last updated[5]	asking $12,995

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 35 live listings, as of 17 Nov 2026
[5] Live public dealer listings on Cardog, as of 17 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.