Register entry, as of 29 October 2026 Listed for sale Record ID 3767b5f5e99f

2018 Volkswagen Tiguan 4Motion SEL Premium

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VV	4B7AX	5	J	M	006764
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen De Mexico Sa…	Tiguan · 2.0 L	Verified	2018	Puebla	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Tiguan	Drive	AWD
Trim	4Motion SEL Premium	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Sport Utility Vehicle	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/tiguan/2018

10 recalls listed by Transport Canada for this model year

Steering

2026439 11 Sep 2026

Issue: On certain vehicles, one of the bolts that attaches the steering rack to the subframe could corrode and break. If this happens, the steering rack housing could break and cause a loss of steering control. Safety Risk: A loss of steering control could create a risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the right steering rack mounting bolt.

Structure

2022170 6 Apr 2022

Issue: This recall is for accessory rear hatch spoilers that were installed on a new vehicle or sold as an accessory part at a Volkswagen dealership. On certain vehicles, the rear spoiler might not be properly attached to the hatch. As a result, the spoiler could detach from the vehicle while driving. Safety Risk: A spoiler that detaches from the vehicle could create a hazard for other drivers and nearby people. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to replace the rear hatch spoiler.

Seats and restraints

2020562 20 Nov 2020

Issue: On certain vehicles, there could be a problem with the driver and/or front passenger seat belt. As a result, the seat belts could break in a crash. Safety Risk: A seat belt that breaks in a crash could create an increased risk of injury. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front seat belts. The driver and front passenger seat belt will be replaced, if necessary.

Suspension

2019116 6 Mar 2019

Issue: On certain vehicles, the rear suspension coil springs may not have been properly manufactured and could break over time. This could cause damage to a rear tire, resulting in rapid air loss and/or tire failure. Safety Risk: A rear tire failure could affect vehicle control. Additionally, a broken coil spring could also create a road hazard for other motorists. Both of these conditions may increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have both of the rear axle coil springs replaced. If a broken coil spring is found, the rear tires should be inspected for damage and replaced as required.

Lights and instruments

2018644 21 Nov 2018

Certain vehicles do not to conform to Canada Motor Vehicle Safety Standard (CMVSS) 114 - Theft Protection and Rollaway Prevention. Due to incorrect programming, the vehicle may fail to provide an audible warning when a driver opens their door after turning off the ignition, and the key is left in the ignition switch. This could increase the risk of vehicle theft. Correction: Dealers will reprogram the instrument cluster.

Structure

2018374 13 Jul 2018

On certain vehicles, the LED module for the panoramic sunroof ambient light bar may overheat, increasing the risk of a fire causing injury and/or damage to property. Correction: Dealers will install in-line fuses for the left and right panoramic sunroof ambient light LED modules.

4 more on the model-year record, cardog.app/tools/recalls/volkswagen/tiguan/2018

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 14 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $13,995[5], $3,000 under the median of $16,995[4].



Lowest ask	$9,995
Middle half	$15,292 – $18,998
Median ask	$16,995
This car	$13,995

Same configuration · 49 live listings · as of 29 Oct 2026

OTHER 2018 VOLKSWAGEN TIGUAN LISTINGS [5]

Tecumseh, ON · 141,094 km	$14,606
Orangeville, ON · 127,832 km	$19,472
Repentigny, QC · 132,100 km	$14,480
North Vancouver, BC · 86,434 km	$21,005
Saskatoon, SK · 166,512 km	$15,269
Chatham, ON · 198,708 km	$15,249

§4 EVENTS

2018 **Model year 2018**[1]
Assembly plant Puebla, Mexico

18 Oct 2017	Transport Canada recall 2017507[2] Issued for the model year · Lights and instruments
25 Apr 2018	Transport Canada recall 2018205[2] Issued for the model year · Suspension
16 May 2018	Transport Canada recall 2018265[2] Issued for the model year · Suspension
6 Jun 2018	Transport Canada recall 2018296[2] Issued for the model year · Airbag
13 Jul 2018	Transport Canada recall 2018374[2] Issued for the model year · Structure
21 Nov 2018	Transport Canada recall 2018644[2] Issued for the model year · Lights and instruments
6 Mar 2019	Transport Canada recall 2019116[2] Issued for the model year · Suspension
20 Nov 2020	Transport Canada recall 2020562[2] Issued for the model year · Seats and restraints
6 Apr 2022	Transport Canada recall 2022170[2] Issued for the model year · Structure
11 Sep 2026	Transport Canada recall 2026439[2] Issued for the model year · Steering
28 Oct 2026	Listed for sale, Toronto, ON[5] Ryder Auto Sales · asking $13,995
29 Oct 2026	Listing last updated[5] asking $13,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 49 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.