Register entry, as of 29 October 2026 Listed for sale Record ID 0ef962d131f9

# 2025 Volkswagen Tiguan 4Motion S

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3VV | BR7RM | 7 | S | M | 063725 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Volkswagen De Mexico Sa... | Tiguan · 2.0 L | Verified | 2025 | Puebla | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2025 | Engine | 2.0 L, 4 cylinders |
| Make | Volkswagen | Fuel | Gasoline |
| Model | Tiguan | Drive | Not in the decode |
| Trim | 4Motion S | Maker | VOLKSWAGEN DE MEXICO SA DE CV |
| Body | Sport Utility Vehicle | Plant | Puebla, Puebla, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/tiguan/2025

**4** recalls listed by Transport Canada for this model year

### Electrical

2026434 10 Sep 2026

Issue: On certain vehicles, a software problem could cause the body control module (BCM) to reset while driving. As a result, the ignition could switch off and cause a loss of power to the wheels. It could also cause a loss of certain controls, warning lights, malfunction tell-tales and rearview camera system. Safety Risk: A loss of power to the wheels, exterior lights that don't work, and/or controls, warnings and tell-tales that don't display could increase the risk of a crash. A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up, which could also increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to update the BCM software.

### Seats and restraints

2025679 10 Dec 2025

Issue: On certain vehicles, the wiring for the passenger occupant detection system (PODS) may not have been manufactured properly. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause an error message to display on the instrument panel and a warning chime to sound. The airbag indicator light would also display "passenger airbag off". Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Volkswagen advises that you shouldn't use the front passenger seat if a PODS error message displays on the instrument panel or if the airbag indicator light displays "passenger airbag off" with an occupant in the seat. Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to repair the passenger-front seat wiring harness.

### Suspension

2025421 13 Aug 2025

Issue: On a small number of vehicles, the rear tie rod bolt(s) may not have been tightened properly. As a result, the bolt(s) could loosen and cause a loss of vehicle stability. Safety Risk: A loss of vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the rear tie rod bolt(s).

### Visual system

2025066 12 Feb 2025

Issue: On certain vehicles, a problem with the camera control unit could cause the rearview camera image not to display after shifting into reverse or after activating the parking assistance function. Canadian regulations require the rearview image to display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to update the camera control unit software.

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
www.vw.ca/en/owners-and-drivers/recalls.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $37,285[5], $3,305 over the median of $33,980[4].

| | |
|---|---|
| Lowest ask | $28,995 |
| Middle half | $32,495 – $35,995 |
| Median ask | $33,980 |
| This car | $37,285 |

Same configuration · 29 live listings · as of 29 Oct 2026

OTHER 2025 VOLKSWAGEN TIGUAN LISTINGS [5]

| | |
|---|---|
| Yarmouth, NS · 11,131 km | $36,977 |
| Nanaimo, BC · 28,327 km | $44,377 |
| Kentville, NS · 11,131 km | $36,977 |
| Nanaimo, BC · 29,771 km | $37,977 |
| Notre-Dame-Des-Prairies, QC · 9,800 km | $35,995 |
| Kentville, NS · 11,131 km | $36,977 |

## §4 EVENTS

| | |
|---|---|
| 2025 | Model year 2025[1]<br>Assembly plant Puebla, Puebla, Mexico |
| 12 Feb 2025 | Transport Canada recall 2025066[2]<br>Issued for the model year · Visual system |
| 13 Aug 2025 | Transport Canada recall 2025421[2]<br>Issued for the model year · Suspension |
| 10 Dec 2025 | Transport Canada recall 2025679[2]<br>Issued for the model year · Seats and restraints |
| 4 Mar 2026 | Listed for sale, Vancouver, BC[5]<br>Vancouver Volkswagen · asking $37,285 |

| | |
|---|---|
| 10 Sep 2026 | Transport Canada recall 2026434[2]<br>Issued for the model year · Electrical |
| 29 Oct 2026 | Listing last updated[5]<br>asking $37,285 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 29 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.