Register entry, as of 29 November 2026 Listed for sale Record ID 373f57a50610

2017 Volkswagen Golf S, Wolfsburg, SE, SEL

1.8 L, 4 cylinders · FWD · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VW	217AU	0	H	M	052184
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen De Mexico Sa…	Golf · 1.8 L	Verified	2017	Puebla	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	1.8 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Golf	Drive	FWD
Trim	S, Wolfsburg, SE, SEL	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Hatchback	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/golf/2017

6 recalls listed by Transport Canada for this model year

Fuel system

2024095 14 Feb 2024

Issue: On certain vehicles, a seal for the suction jet pump inside the fuel tank could fail. As a result, fuel may flow directly into the evaporative emission control system (EVAP). If this happens, fuel could leak from the charcoal canister. Note: This problem could cause a fuel odor, the fuel nozzle to stop early and/or fuel to spill when refueling. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the suction jet pump.

Fabrics

2021326 26 May 2021

Issue: On certain models, the chrome layer could peel off of the trim located around the gear shift cover. If this happens, sharp edges can be created. Safety Risk: Exposed sharp edges can create the risk of a cut. Corrective Actions: Volkswagen will contact owners by mail and instruct you to take your vehicle to a dealer to replace the gear shift cover trim frame.

Label

2020353 4 Aug 2020

Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.

Suspension

2019116 6 Mar 2019

Issue: On certain vehicles, the rear suspension coil springs may not have been properly manufactured and could break over time. This could cause damage to a rear tire, resulting in rapid air loss and/or tire failure. Safety Risk: A rear tire failure could affect vehicle control. Additionally, a broken coil spring could also create a road hazard for other motorists. Both of these conditions may increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have both of the rear axle coil springs replaced. If a broken coil spring is found, the rear tires should be inspected for damage and replaced as required.

Powertrain

2018371 11 Jul 2018

On certain vehicles, the park position switch may malfunction due to a problem with the electrical contacts. This could allow for removal of the ignition key without the shift lever being in the Park (P) position. If the parking brake is not applied, this could result in unintended vehicle movement, which could increase the risk of crash causing injury and/or damage to property. Correction: Dealers will install an additional park position switch and circuit board.

Label

2017053 3 Feb 2017

Certain vehicles with factory installed 15-inch tires may fail to comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 110 - Tire Selection and Rims. The certification label incorrectly states the sidewall height for the rear tires, which is contrary to the requirements of the standard. The rear tire specification on the label should read 195/65 R15. Correction: Dealers will install a new tire information label with correct specifications.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $14,949[5], $2,007 over the median of $12,942[4].



Lowest ask	$6,995
Middle half	$11,612 – $15,437
Median ask	$12,942
This car	$14,949

Same configuration · 22 live listings · as of 29 Nov 2026

OTHER 2017 VOLKSWAGEN GOLF LISTINGS [5]

Vaughan, ON · 136,000 km	$11,998
Duncan, BC · 135,574 km	$11,995
Kitchener, ON · 200,827 km	$9,999
St-Basile-Le-Grand, QC · 114,622 km	$9,790
Stratford, ON · 45,140 km	$14,800
Calgary, AB · 50,310 km	$25,295

§4 EVENTS

2017 Model year 2017[1]
Assembly plant Puebla, Mexico

3 Feb 2017	Transport Canada recall 2017053[2] Issued for the model year · Label
11 Jul 2018	Transport Canada recall 2018371[2] Issued for the model year · Powertrain
6 Mar 2019	Transport Canada recall 2019116[2] Issued for the model year · Suspension
4 Aug 2020	Transport Canada recall 2020353[2] Issued for the model year · Label
26 May 2021	Transport Canada recall 2021326[2] Issued for the model year · Fabrics
14 Feb 2024	Transport Canada recall 2024095[2] Issued for the model year · Fuel system
19 Nov 2026	Listed for sale, Calgary, AB[5] Wheaton Honda West · asking $14,949
28 Nov 2026	Listing last updated[5] asking $14,949

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 22 live listings, as of 29 Nov 2026

[5] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.