Register entry, as of 27 October 2026 Listed for sale Record ID f5f89349e42b

2016 Volkswagen Jetta S

1.4 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VW	267AJ	9	G	M	293263
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen De Mexico Sa…	Jetta · 1.4 L	Verified	2016	Puebla	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	1.4 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Jetta	Drive	Not in the decode
Trim	S	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Sedan	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/jetta/2016

5 recalls listed by Transport Canada for this model year

Heater and defroster

2024648 30 Oct 2024

Issue: Volkswagen Group Canada is conducting a parts recovery campaign targeting 2012-2016 Volkswagen vehicles equipped with a TDI (diesel) engine built between May 25, 2011 and June 1, 2016. The auxiliary heater elements are being recovered to aid in Volkswagen's analysis in support of Transport Canada defect investigation file no. 3280-15-10. Note: This action is not being conducted under the requirements of the Motor Vehicle Safety Act. For the 2016 model year Jetta, only the Jetta Hybrid model is involved in this parts recovery program. Safety Risk: No safety defect has been identified with these auxiliary heater elements. Corrective Actions: Volkswagen will notify owners by mail and advise them to take their vehicle to a dealership to replace the auxiliary heater element at no charge.

Fuel system

2020502 21 Oct 2020

Issue: On certain vehicles, the fuel rail bolts could become loose over time. If this happens, there could be a fuel odour or fuel leak in the engine compartment. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel rail bolts and, if necessary, replace the fuel rail.

Label

2020353 4 Aug 2020

Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.

Powertrain

2019423 22 Aug 2019

Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.

Engine

2015504 23 Oct 2015

On certain vehicles, the camshaft lobe which actuates the vacuum pump may fail, causing the pump to fail to deliver further vacuum supply to the brake booster, potentially increasing stopping distances. This would also result in a reduction in available engine power. These issues could increase the risk of a crash causing injury and/or damage to property. Note: This issue would result in the Engine Malfunction Indicator Light (MIL) illuminating. Correction: Dealers will update the engine control module (ECM) software.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $9,999[5], $2 over the median of $9,997[4].

Lowest ask	$4,950
Middle half	$8,991 – $12,666
Median ask	$9,997
This car	$9,999

Same model year · 30 live listings · as of 27 Oct 2026

OTHER 2016 VOLKSWAGEN JETTA LISTINGS [5]

Québec, QC · 124,000 km	$9,995
Lachute, QC · 102,615 km	$9,995
Saint-Lin-Laurentides, QC · 190,208 km	$8,995
Milton, ON · 157,500 km	$11,995
Vaudreuil-Dorion, QC · 212,000 km	$7,990
Scarborough, ON · 202,500 km	$7,999

§4 EVENTS

2016	Model year 2016[1] Assembly plant Puebla, Mexico
23 Oct 2015	Transport Canada recall 2015504[2] Issued for the model year · Engine
22 Aug 2019	Transport Canada recall 2019423[2] Issued for the model year · Powertrain

4 Aug 2020	Transport Canada recall 2020353[2] Issued for the model year · Label
21 Oct 2020	Transport Canada recall 2020502[2] Issued for the model year · Fuel system
30 Oct 2024	Transport Canada recall 2024648[2] Issued for the model year · Heater and defroster
16 Oct 2026	Listed for sale, Brampton, ON[5] Bramgate Pre-Owned Centre · asking $9,999
27 Oct 2026	Listing last updated[5] asking $9,999

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 30 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.