Register entry, as of 27 October 2026 Listed for sale Record ID e07eb3fb683f

2017 Volkswagen Jetta S

1.4 L, 4 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VW	2B7AJ	0	H	M	325563
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen De Mexico Sa...	Jetta · 1.4 L	Verified	2017	Puebla	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	1.4 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Jetta	Drive	FWD
Trim	S	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Sedan	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/jetta/2017

6 recalls listed by Transport Canada for this model year

Fuel system

2020502 21 Oct 2020

Issue: On certain vehicles, the fuel rail bolts could become loose over time. If this happens, there could be a fuel odour or fuel leak in the engine compartment. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel rail bolts and, if necessary, replace the fuel rail.

Label

2020353 4 Aug 2020

Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.

Powertrain

2019423 22 Aug 2019

Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.

Label
2017112 2 Mar 2017

Certain vehicles may not comply with Canadian Motor Vehicle Safety Regulations. The tire information label may have incorrect vehicle load rating values. This could result in vehicle overloading, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will apply a revised label. Note: This recall affects Jetta GLI models only.

Label
2017111 2 Mar 2017

Certain vehicles may not comply with Canadian Motor Vehicle Safety Regulations. The tire information label may have incorrect vehicle load rating values. This could result in vehicle overloading, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will apply a revised label.

Engine
2017052 3 Feb 2017

On certain vehicles, improper casting of the engine block may cause the engine to seize/lock up. A seizing engine may lead to a loss of vehicle control, increasing the risk of a crash causing injury and/or damage to property. Correction: Affected vehicles will be bought back from the owner. If the owner refuses, a replacement engine will be installed.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $7,995[5], $2,500 under the median of $10,495[4].

Lowest ask	$4,999
Middle half	$8,495 – $13,995
Median ask	$10,495
This car	$7,995

Same configuration · 13 live listings · as of 27 Oct 2026

OTHER 2017 VOLKSWAGEN JETTA LISTINGS [5]

Saskatoon, SK · 145,000 km	$12,999
Vaudreuil-Dorion, QC · 175,940 km	$7,895
Saint-Georges, QC · 249,672 km	$5,995
Waterloo, ON · 133,000 km	$13,995
Lévis, QC · 169,000 km	$7,950
St-Hubert, QC · 162,611 km	$5,995

§4 EVENTS

2017	Model year 2017[1] Assembly plant Puebla, Mexico
3 Feb 2017	Transport Canada recall 2017052[2] Issued for the model year · Engine

2 Mar 2017	Transport Canada recall 2017112[2] Issued for the model year · Label
2 Mar 2017	Transport Canada recall 2017111[2] Issued for the model year · Label
22 Aug 2019	Transport Canada recall 2019423[2] Issued for the model year · Powertrain
4 Aug 2020	Transport Canada recall 2020353[2] Issued for the model year · Label
21 Oct 2020	Transport Canada recall 2020502[2] Issued for the model year · Fuel system
24 Oct 2026	Listed for sale, Mascouche, QC[5] Autoclic · asking $7,995
27 Oct 2026	Listing last updated[5] asking $7,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 13 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.