Register entry, as of 29 October 2026 Listed for sale Record ID e4fd809b9a96

# 2014 Volkswagen Jetta GLI

1.9 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3VW | 4S7AJ | 6 | E | M | 357129 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Volkswagen De Mexico Sa… | Jetta · 1.9 L | Verified | 2014 | Puebla | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2014 | Engine | 1.9 L, 4 cylinders |
| Make | Volkswagen | Fuel | Gasoline |
| Model | Jetta | Drive | Not in the decode |
| Trim | GLI | Maker | VOLKSWAGEN DE MEXICO SA DE CV |
| Body | Sedan | Plant | Puebla, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/jetta/2014

**6** recalls listed by Transport Canada for this model year

### Heater and defroster

2024648 30 Oct 2024

Issue: Volkswagen Group Canada is conducting a parts recovery campaign targeting 2012-2016 Volkswagen vehicles equipped with a TDI (diesel) engine built between May 25, 2011 and June 1, 2016. The auxiliary heater elements are being recovered to aid in Volkswagen's analysis in support of Transport Canada defect investigation file no. 3280-15-10. Note: This action is not being conducted under the requirements of the Motor Vehicle Safety Act. For the 2016 model year Jetta, only the Jetta Hybrid model is involved in this parts recovery program. Safety Risk: No safety defect has been identified with these auxiliary heater elements. Corrective Actions: Volkswagen will notify owners by mail and advise them to take their vehicle to a dealership to replace the auxiliary heater element at no charge.

### Label

2020353 4 Aug 2020

Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.

### Powertrain

2019423 22 Aug 2019

Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.

### Fuel system
2014575 17 Dec 2014

On certain vehicles, a sealing cap at the fuel rail may fail to seal, allowing fuel to leak into the engine compartment during engine operation. Leaking fuel, in the presence of an ignition source, could lead to a fire causing injury and/or damage to property. Correction: Dealers will inspect, and if necessary, replace the fuel rail.

### Powertrain
2014136 16 Apr 2014

On certain vehicles equipped with 1.8T engines and torque-converter (non-DSG) automatic transmissions, out of specification transmission cooler sealing O-rings may allow transmission fluid to leak in proximity to hot surfaces. This could increase the risk of a fire, potentially causing injury and/or property damage. Correction: Dealers will replace affected O-rings.

### Accessories
2014068 5 Mar 2014

On certain vehicles equipped with a factory installed block heater, the block heater could overheat while in use. This could result in a fire causing injury and/or property damage. Correction: Dealers will replace the block heater. Owners are advised to stop using the block heater in the interim.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $11,895[5], $4,795 over the median of $7,100[4].




| | |
|---|---|
| Lowest ask | $2,700 |
| Middle half | $6,110 – $9,437 |
| Median ask | $7,100 |
| This car | $11,895 |

Same model year · 38 live listings · as of 29 Oct 2026

#### OTHER 2014 VOLKSWAGEN JETTA LISTINGS [5]

| | |
|---|---|
| Pickering, ON · 247,291 km | $2,999 |
| Montréal, QC · 145,835 km | $6,995 |
| Saint-Hyacinthe, QC · 269,920 km | $5,222 |
| Kelowna, BC · 145,796 km | $12,977 |
| Middle Sackville, NS · 136,458 km | $10,995 |
| Milton, ON · 210,991 km | $5,999 |

## §4 EVENTS

| | |
|---|---|
| 2014 | Model year 2014[1]<br>Assembly plant Puebla, Mexico |
| 5 Mar 2014 | Transport Canada recall 2014068[2]<br>Issued for the model year · Accessories |

| | |
|---|---|
| 16 Apr 2014 | Transport Canada recall 2014136[2]<br>Issued for the model year · Powertrain |
| 17 Dec 2014 | Transport Canada recall 2014575[2]<br>Issued for the model year · Fuel system |
| 22 Aug 2019 | Transport Canada recall 2019423[2]<br>Issued for the model year · Powertrain |
| 4 Aug 2020 | Transport Canada recall 2020353[2]<br>Issued for the model year · Label |
| 30 Oct 2024 | Transport Canada recall 2024648[2]<br>Issued for the model year · Heater and defroster |
| 4 Oct 2026 | Listed for sale, North Vancouver, BC[5]<br>Lexa Auto Sales Ltd. · asking $11,895 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $11,895 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 38 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.