

2019 Volkswagen Jetta GLI (S, 35th Anniversary Ed., Autobahn)

2.0 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VW

WMI 1-3

Volkswagen De Mexico Sa...

6T7BU

DESCRIPTOR 4-8

Jetta · 2.0 L

5

CHECK 9

Verified

K

YEAR 10

2019

M

PLANT 11

Puebla

234920

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Jetta	Drive	Not in the decode
Trim	GLI (S, 35th Anniversary Ed., Autobahn)	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Sedan	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/jetta/2019

11 recalls listed by Transport Canada for this model year

Fuel system

2024095 14 Feb 2024

Issue: On certain vehicles, a seal for the suction jet pump inside the fuel tank could fail. As a result, fuel may flow directly into the evaporative emission control system (EVAP). If this happens, fuel could leak from the charcoal canister. Note: This problem could cause a fuel odor, the fuel nozzle to stop early and/or fuel to spill when refueling. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the suction jet pump.

Electrical

2023487 31 Aug 2023

Issue: On certain vehicles equipped with a key ignition switch, a fuse in the ignition switch could fail. If this happens, the vehicle can lose power while driving and cause the engine to stall. This could also cause the airbag system and turn signals not to work. Safety Risk: A sudden loss of power could increase the risk of a crash. An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the ignition switch.

Label

2020353 4 Aug 2020

Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.



Lights and instruments

2019620 11 Dec 2019

Issue: On certain cars, the right-front daytime running light (DRL) may not work or may not be bright enough to meet Canadian regulations.

Note: This recall replaces Transport Canada recall 2019-292. Vehicles that were repaired under that recall also require this repair. Safety Risk: A daytime running light that is dimmed or not working could make the car less visible to others and increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your car to a dealer to inspect the right-front headlight. The heat sink or complete right headlight will be replaced as necessary.

Suspension

2019619 11 Dec 2019

Issue: On a small number of Jetta GLI models, one or both of the front wheel bearings could be defective. This could lead to poor driving performance and/or cause a wheel to break. Safety Risk: A sudden change in vehicle handling or a broken wheel could cause a loss of control and increase the risk of a crash. Corrective Actions: Volkswagen will contact owners by telephone and instruct you to stop driving your vehicle. Volkswagen will arrange free towing to the nearest dealership. The front wheel bearing assemblies, wheels, and wheel bolts will be replaced.

Lights and instruments

2019292 13 Jun 2019

Note: This recall is superseded by recall 2019-620. Please see recall 2019620 for more information. Issue: On certain cars, the right-front daytime running light (DRL) may not work or may not be bright enough to meet Canadian regulations. Safety Risk: A daytime running light that is dimmed or not working could make the car less visible to other drivers and increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their car to a dealer to replace the right headlight.

5 more on the model-year record, cardog.app/tools/recalls/volkswagen/jetta/2019

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.

Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.

www.vw.ca/en/owners-and-drivers/recalls.html

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$21,988^[5], \$1,993 over the median of \$19,995^[4].



Lowest ask	\$9,991
Middle half	\$17,744 – \$21,882
Median ask	\$19,995
This car	\$21,988

Same configuration · 11 live listings · as of 29 Oct 2026

OTHER 2019 VOLKSWAGEN JETTA LISTINGS [5]

Orangeville, ON · 237,830 km	\$9,991
Owen Sound, ON · 146,530 km	\$12,615
Edmonton, AB · 94,920 km	\$18,875
Winnipeg, MB · 94,920 km	\$19,999
Winnipeg, MB · 94,920 km	\$19,999
Bowmanville, ON · 40,462 km	\$21,995



§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Puebla, Mexico
26 Sep 2018	Transport Canada recall 2018534 ^[2] Issued for the model year · Lights and instruments
21 Nov 2018	Transport Canada recall 2018644 ^[2] Issued for the model year · Lights and instruments
19 Dec 2018	Transport Canada recall 2018717 ^[2] Issued for the model year · Suspension
19 Feb 2019	Transport Canada recall 2019074 ^[2] Issued for the model year · Airbag
6 Mar 2019	Transport Canada recall 2019116 ^[2] Issued for the model year · Suspension
13 Jun 2019	Transport Canada recall 2019292 ^[2] Issued for the model year · Lights and instruments
11 Dec 2019	Transport Canada recall 2019620 ^[2] Issued for the model year · Lights and instruments
11 Dec 2019	Transport Canada recall 2019619 ^[2] Issued for the model year · Suspension
4 Aug 2020	Transport Canada recall 2020353 ^[2] Issued for the model year · Label
31 Aug 2023	Transport Canada recall 2023487 ^[2] Issued for the model year · Electrical
14 Feb 2024	Transport Canada recall 2024095 ^[2] Issued for the model year · Fuel system
28 Oct 2026	Listed for sale, Mississauga, ON ^[5] Leopard Motors Inc · asking \$21,988
29 Oct 2026	Listing last updated ^[5] asking \$21,988

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 11 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

