Register entry, as of 28 October 2026 Listed for sale Record ID efe2a867693c

# 2020 Volkswagen Jetta S, SE, R-Line

1.4 L, 4 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3VW | CB7BU | 4 | L | M | 014210 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Volkswagen De Mexico Sa… | Jetta · 1.4 L | Verified | 2020 | Puebla | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | 1.4 L, 4 cylinders |
| Make | Volkswagen | Fuel | Gasoline |
| Model | Jetta | Drive | FWD |
| Trim | S, SE, R-Line | Maker | VOLKSWAGEN DE MEXICO SA DE CV |
| Body | Sedan | Plant | Puebla, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/jetta/2020

**7** recalls listed by Transport Canada for this model year

### Fuel system

2024095 14 Feb 2024

Issue: On certain vehicles, a seal for the suction jet pump inside the fuel tank could fail. As a result, fuel may flow directly into the evaporative emission control system (EVAP). If this happens, fuel could leak from the charcoal canister. Note: This problem could cause a fuel odor, the fuel nozzle to stop early and/or fuel to spill when refueling. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the suction jet pump.

### Electrical

2023487 31 Aug 2023

Issue: On certain vehicles equipped with a key ignition switch, a fuse in the ignition switch could fail. If this happens, the vehicle can lose power while driving and cause the engine to stall. This could also cause the airbag system and turn signals not to work. Safety Risk: A sudden loss of power could increase the risk of a crash. An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the ignition switch.

### Airbag

2021404 30 Jun 2021

Issue: On certain vehicles, the airbag control module may not be mounted properly. As a result, the airbag may not inflate in a crash, or it could inflate suddenly while driving. Safety Risk: An airbag that does not inflate properly could increase the risk of injury in a crash. Additionally, an airbag that inflates suddenly while driving could increase the risk of injury or a crash. Corrective Action: Volkswagen will notify owners by mail and instruct you to bring your vehicle to a dealer to replace the airbag control module.

### Seats and restraints

2021031 27 Jan 2021

Issue: On certain vehicles, the driver's seat frame may not have been properly welded. As a result, the seat frame could fail and move in a crash. Safety Risk: A seat frame that fails could cause an increased risk of injury in a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the driver's seat. The seat frame will be replaced, as necessary.

### Brakes

2021014 20 Jan 2021

Issue: On certain vehicles, a front brake hose may be too long and could rub against the steering mechanism. This can cause damage to the hose that could result in a brake fluid leak. If this happens, a driver may have reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front brake hose. It will be replaced, if necessary.

### Seats and restraints

2020392 26 Aug 2020

Issue: On certain vehicles, parts of the front seat frame and backrest adjuster may not have been properly welded. As a result, the backrest adjustment could break in a rear-end crash and allow to seat to move. Safety Risk: A seatback that fails could cause an increased risk of injury in a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the driver and passenger front seats. The seatback frames will be replaced, as necessary.

1 more on the model-year record, cardog.app/tools/recalls/volkswagen/jetta/2020

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $22,479[5], $7,232 over the median of $15,247[4].

| | |
|---|---|
| Lowest ask | $11,995 |
| Middle half | $14,745 – $18,616 |
| Median ask | $15,247 |
| This car | $22,479 |

Same configuration · 12 live listings · as of 28 Oct 2026

#### OTHER 2020 VOLKSWAGEN JETTA LISTINGS [5]

| | |
|---|---|
| Granby, QC · 96,425 km | $15,995 |
| Pembroke, ON · 137,130 km | $16,944 |
| Vernon, BC · 155,428 km | $17,995 |
| Sarnia, ON · 169,027 km | $14,998 |
| Thunder Bay, ON · 80,944 km | $19,400 |
| Dollard-Des Ormeaux, QC · 116,000 km | $15,495 |

## §4 EVENTS

2020 Model year 2020[1]
Assembly plant Puebla, Mexico

| | |
|---|---|
| 17 Jun 2020 | Transport Canada recall 2020275[2]<br>Issued for the model year · Brakes |
| 26 Aug 2020 | Transport Canada recall 2020392[2]<br>Issued for the model year · Seats and restraints |
| 20 Jan 2021 | Transport Canada recall 2021014[2]<br>Issued for the model year · Brakes |
| 27 Jan 2021 | Transport Canada recall 2021031[2]<br>Issued for the model year · Seats and restraints |
| 30 Jun 2021 | Transport Canada recall 2021404[2]<br>Issued for the model year · Airbag |
| 31 Aug 2023 | Transport Canada recall 2023487[2]<br>Issued for the model year · Electrical |
| 14 Feb 2024 | Transport Canada recall 2024095[2]<br>Issued for the model year · Fuel system |
| 24 Sep 2026 | Listed for sale, North York, ON[5]<br>SUPERB AUTO SALES · asking $22,479 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $22,479 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 12 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.