

Register entry, as of 28 October 2026

Listed for sale

Record ID 76e254e38278

2018 Volkswagen Beetle SE

2.0 L, 4 cylinders · FWD · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3VW

WMI 1-3

Volkswagen De Mexico Sa...

JD7AT

DESCRIPTOR 4-8

Beetle · 2.0 L

3

CHECK 9

Verified

J

YEAR 10

2018

M

PLANT 11

Puebla

723976

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.0 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Beetle	Drive	FWD
Trim	SE	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Coupe	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/beetle/2018

3 recalls listed by Transport Canada for this model year

Airbag 2024649 30 Oct 2024

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the driver-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-front airbag. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

Powertrain 2019423 22 Aug 2019

Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.

Brakes 2018292 1 Jun 2018

On certain vehicles, a problem with the brake system may cause gas bubbles to form in the brake fluid. This could cause a soft brake pedal feel and a reduction in brake performance, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will bleed the front or rear brakes as necessary. Note: In the interim, owners are advised to stop driving their vehicle until the defect has been repaired. Affected owners should call Volkswagen's Roadside Assistance number at 1-800-411-6688.



Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
www.vw.ca/en/owners-and-drivers/recalls.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$23,995^[5], \$3,077 over the median of \$20,918^[4].



Lowest ask	\$14,995
Middle half	\$19,532 – \$21,497
Median ask	\$20,918
This car	\$23,995

Same configuration · 8 live listings · as of 28 Oct 2026

OTHER 2018 VOLKSWAGEN BEETLE LISTINGS ^[5]

Oakville, ON · 70,931 km	\$20,998
Georgetown, ON · 136,080 km	\$20,887
Sorel-Tracy, QC · 95,920 km	\$18,495
Kemptville, ON · 95,382 km	\$19,995
Owen Sound, ON · 89,004 km	\$18,142
Penticton, BC · 86,142 km	\$26,995

§4 EVENTS

2018	Model year 2018 ^[1] Assembly plant Puebla, Mexico
1 Jun 2018	Transport Canada recall 2018292 ^[2] Issued for the model year · Brakes
22 Aug 2019	Transport Canada recall 2019423 ^[2] Issued for the model year · Powertrain
30 Oct 2024	Transport Canada recall 2024649 ^[2] Issued for the model year · Airbag
25 Oct 2026	Listed for sale, Ancaster, ON ^[5] Village Auto of Ancaster · asking \$23,995
28 Oct 2026	Listing last updated ^[5] asking \$23,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.



SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 8 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

