

Register entry, as of 27 October 2026

Listed for sale

Record ID 69e5d8dbaa93

2006 Volkswagen Jetta 2.5 TDI

1.9 L, 4 cylinders · Sedan · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

3VW

WMI 1-3

Volkswagen De Mexico Sa...

RT81K

DESCRIPTOR 4-8

Jetta · 1.9 L

9

CHECK 9

Verified

6

YEAR 10

2006

M

PLANT 11

Puebla

772318

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2006	Engine	1.9 L, 4 cylinders
Make	Volkswagen	Fuel	Diesel
Model	Jetta	Drive	Not in the decode
Trim	2.5 TDI	Maker	VOLKSWAGEN DE MEXICO SA DE CV
Body	Sedan	Plant	Puebla, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/jetta/2006

6 recalls listed by Transport Canada for this model year

Fuel system 2010444 10 Dec 2010

On certain Golf, Golf wagon, Jetta and Rabbit equipped with a 2.5L Engine, a small plastic tab located on the windshield washer fluid reservoir may chafe against an underhood fuel supply line. If chafing occurs fuel leakage could develop which, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will inspect the affected vehicles and, if necessary, replace the fuel line. In addition, as a preventive measure, the plastic tab from the windshield washer fluid reservoir will be removed.

Structure 2009141 14 May 2009

On certain vehicles, driveshaft cover plate screws may not have been torqued properly during vehicle assembly. Should they loosen, a knocking sound may be heard while the vehicle is in motion. In the worst case, the driveshaft screws could loosen to the point where the driveshaft detaches from the gearbox. If the vehicle is moving when this happens, the detached driveshaft could cause damage to the gearbox housing. A damaged gearbox housing could leak gearbox oil onto the street and create a risk of vehicle crash for both the driver and other motorists. This could result in property damage, personal injury or death. Correction: Dealers will inspect and, if necessary, replace the driveshaft screws.

Lights and instruments 2007306 18 Sep 2007

Certain vehicles fail to comply with the requirements of CMVSS 108 - Lamps, Reflective Devices and Associated Equipment. 1). The required cap designed to disable the headlamp horizontal aim may not have been installed during vehicle assembly. 2). A cap may have been inadvertently installed to disable the vertical aiming screw. 3). An adjustment mechanism allows aiming of the low beam relative to the high beam. Correction: Dealers will affect repairs.



Other

2007210 22 Jun 2007

Certain vehicles may have a small plastic tab located on the windshield washer fluid reservoir that may chafe against the underhood fuel supply line. If this happens, the chaffing could cause a fuel leak over time. Fuel leakage, in the presence of an ignition source, may result in a fire. Correction: Dealers will inspect and, if necessary, replace the underhood fuel supply line. As a preventative measure, dealers will also remove the plastic tab from the windshield washer fluid reservoir.

Lights and instruments

2006122 24 May 2006

On certain Golf, GTI, Jetta, Jetta wagon, New Beetle, New Beetle convertible, Passat and Passat wagon, the brake lamp switch may malfunction. If this happens, the brake lamps could become inoperative; or could come on and stay on, even though the vehicle is parked. Correction: Dealers will replace the brake lamp switch with a newly revised version. This action includes vehicles previously affected by Transport Canada recall 03-184 and 04-075. The switch installed during this prior repair may not function properly. Note: parts available December 2006.

Fuel system

2005192 29 Jun 2005

On certain vehicles equipped with a 2.5L gasoline engine, a fuel supply line clamp located in the engine compartment may not be positioned properly and could leak. A fuel leak, in the presence of an ignition source, may cause a fire. Correction: Dealers will inspect and, if necessary, replace the subject fuel supply line clamp.

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.


Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.

www.vw.ca/en/owners-and-drivers/recalls.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$3,499^[5], \$2,481 under the median of \$5,980^[4].



Lowest ask	\$3,499
Middle half	\$4,740 – \$8,040
Median ask	\$5,980
This car	\$3,499

Same model year · 3 live listings · as of 27 Oct 2026

OTHER 2006 VOLKSWAGEN JETTA LISTINGS [5]

Grand Forks, BC · 179,071 km	\$5,980
Markham, ON · 139,544 km	\$10,100

§4 EVENTS

2006	Model year 2006 ^[1] Assembly plant Puebla, Mexico
29 Jun 2005	Transport Canada recall 2005192 ^[2] Issued for the model year · Fuel system
24 May 2006	Transport Canada recall 2006122 ^[2] Issued for the model year · Lights and instruments



22 Jun 2007	Transport Canada recall 2007210 ^[2] Issued for the model year · Other
18 Sep 2007	Transport Canada recall 2007306 ^[2] Issued for the model year · Lights and instruments
14 May 2009	Transport Canada recall 2009141 ^[2] Issued for the model year · Structure
10 Dec 2010	Transport Canada recall 2010444 ^[2] Issued for the model year · Fuel system
17 Jun 2026	Listed for sale, Surrey, BC ^[5] RDS Auto Sales · asking \$3,499
25 Oct 2026	Listing last updated ^[5] asking \$3,499

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 3 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

