

Register entry, as of 27 October 2026

Listed for sale

Record ID 65ace5dc4a63

# 2018 Volkswagen Beetle Dune

2.0 L, 4 cylinders · FWD · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**3VW TDAAT 1 J M 517013**

WMI 1-3

Volkswagen De Mexico Sa...

DESCRIPTOR 4-8

Beetle · 2.0 L

CHECK 9

Verified

YEAR 10

2018

PLANT 11

Puebla

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |             |        |                               |
|------------|-------------|--------|-------------------------------|
| Model year | 2018        | Engine | 2.0 L, 4 cylinders            |
| Make       | Volkswagen  | Fuel   | Gasoline                      |
| Model      | Beetle      | Drive  | FWD                           |
| Trim       | Dune        | Maker  | VOLKSWAGEN DE MEXICO SA DE CV |
| Body       | Convertible | Plant  | Puebla, Mexico                |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/volkswagen/beetle/2018](https://cardog.app/tools/recalls/volkswagen/beetle/2018)

## 3 recalls listed by Transport Canada for this model year

### Airbag 2024649 30 Oct 2024

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the driver-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-front airbag. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

### Powertrain 2019423 22 Aug 2019

Issue: On certain vehicles, a build-up of silicate on the shift lever switch could cause the transmission to detect that it is in the Park position when it isn't. This could allow the ignition key to be removed when the transmission is not in the Park position. If the parking brake is not applied, this could allow the car to roll away. Safety Risk: If the transmission position is not displayed correctly, a user may not know that the vehicle is not in the PARK position. If the parking brake is not applied, this could create a risk of a vehicle roll-away and increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have a new shift lever micro switch and control unit installed.

### Brakes 2018292 1 Jun 2018

On certain vehicles, a problem with the brake system may cause gas bubbles to form in the brake fluid. This could cause a soft brake pedal feel and a reduction in brake performance, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will bleed the front or rear brakes as necessary. Note: In the interim, owners are advised to stop driving their vehicle until the defect has been repaired. Affected owners should call Volkswagen's Roadside Assistance number at 1-800-411-6688.




Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.  
Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.  
[www.vw.ca/en/owners-and-drivers/recalls.html](http://www.vw.ca/en/owners-and-drivers/recalls.html)

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

### §3 VALUE <sup>[4]</sup>

This car asks \$33,745<sup>[5]</sup>, \$12,250 over the median of \$21,495<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$14,995            |
| Middle half | \$20,484 – \$24,472 |
| Median ask  | \$21,495            |
| This car    | \$33,745            |

Same model year · 19 live listings · as of 27 Oct 2026

#### OTHER 2018 VOLKSWAGEN BEETLE LISTINGS <sup>[5]</sup>

|                             |          |
|-----------------------------|----------|
| Georgetown, ON · 136,080 km | \$20,887 |
| Sorel-Tracy, QC · 95,920 km | \$18,495 |
| Kemptville, ON · 95,382 km  | \$19,995 |
| Owen Sound, ON · 89,004 km  | \$20,082 |
| Penticton, BC · 86,142 km   | \$26,995 |
| Ancaster, ON · 68,000 km    | \$22,995 |

### §4 EVENTS

|             |                                                                                                                  |
|-------------|------------------------------------------------------------------------------------------------------------------|
| 2018        | Model year 2018 <sup>[1]</sup><br>Assembly plant Puebla, Mexico                                                  |
| 1 Jun 2018  | Transport Canada recall 2018292 <sup>[2]</sup><br>Issued for the model year · Brakes                             |
| 22 Aug 2019 | Transport Canada recall 2019423 <sup>[2]</sup><br>Issued for the model year · Powertrain                         |
| 30 Oct 2024 | Transport Canada recall 2024649 <sup>[2]</sup><br>Issued for the model year · Airbag                             |
| 26 Oct 2026 | Listed for sale, Courtenay, BC <sup>[5]</sup><br>Comox Valley Volkswagen (Sunwest Auto Centre) · asking \$33,745 |

### §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.



---

**SOURCES**

- |                                                                     |                                                                               |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 19 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                               |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                  |

---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

