

Register entry, as of 28 October 2026

Listed for sale

Record ID 4911f93d12af

2007 Mitsubishi Eclipse Spyder

2.4 L, 4 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4A3

WMI 1-3

Mitsubishi Motors North A...

AL25F

DESCRIPTOR 4-8

Eclipse · 2.4 L

2

CHECK 9

Verified

7

YEAR 10

2007

E

PLANT 11

Bloomington-Normal

603398

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	2.4 L, 4 cylinders
Make	Mitsubishi	Fuel	Gasoline
Model	Eclipse	Drive	Not in the decode
Trim	Spyder	Maker	MINITUBISHI MOTORS NORTH AMERICA
Body	Convertible	Plant	Bloomington-Normal, Illinois, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mitsubishi/eclipse/2007

4 recalls listed by Transport Canada for this model year

Brakes	2015219	22 May 2015
On certain vehicles, corrosion may occur in the ABS hydraulic unit due to a reaction between the brake fluid and the surface treatment of the internal valves. If this were to occur and the ABS hydraulic unit is activated, one or more of the valves could seize. This could result in longer brake pedal travel and increased stopping distances, which may increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will flush and clean the hydraulic unit by replacing the brake fluid with higher grade (DOT4) fluid. If module valve movement is determined to be poor, the ABS hydraulic unit will be replaced.		
Other	2008374	10 Oct 2008
On certain vehicles, the bracket that is the anchor point for the left rear fuel tank mounting strap may have been improperly formed during the manufacturing process. This may have caused the metal to spilt in the area where the bolt holds the fuel strap to the underside of the vehicle. In the event the tank is full of fuel and the vehicle is involved in a serious collision the bracket could break and the tank could drop down. This situation could result in a fuel leak and the possibility of a fire. Correction: Dealers will inspect and if necessary install a reinforcement cap to the fuel tank bracket.		
Other	2006280	30 Oct 2006
On certain vehicles, the ignition key interlock cable may have been improperly manufactured. This could allow the automatic transmission gear selector lever to be moved out of the PARK position with the key removed from the ignition switch. If the park brake is not applied, and the gear shift lever is moved out of PARK, the vehicle may roll and result in a vehicle crash. Correction: Dealers will inspect and, if required, replace the interlock cable.		



Structure

2006211 6 Sep 2006


On certain vehicles, the right rear portion of the front crossmember is under-strength. This could allow the passenger side lower control arm to separate from the crossmember, which may result in a loss of steering control and a crash. Correction: Dealers will replace the lower crossmember as necessary.

Listed for the model year, not checked against your VIN. Mitsubishi confirms which apply.
Check your VIN with Mitsubishi Canada or call a Mitsubishi dealer with your VIN.
www.mitsubishi-motors.ca/en/owners/maintenance-service/mitsubishi-recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$2,798^[5], \$6,197 under the median of \$8,995^[4].



Same model year · 1 live listings · as of 28 Oct 2026

OTHER 2007 MITSUBISHI ECLIPSE LISTINGS [5]

High River, AB · 73,348 km \$8,995

§4 EVENTS

2007	Model year 2007 ^[1] Assembly plant Bloomington-Normal, Illinois, United States
6 Sep 2006	Transport Canada recall 2006211 ^[2] Issued for the model year · Structure
30 Oct 2006	Transport Canada recall 2006280 ^[2] Issued for the model year · Other
10 Oct 2008	Transport Canada recall 2008374 ^[2] Issued for the model year · Other
22 May 2015	Transport Canada recall 2015219 ^[2] Issued for the model year · Brakes
29 Oct 2025	Listed for sale, Mount Hope, Hamilton, ON ^[5] Mountain Mitsubishi · asking \$2,798
28 Oct 2026	Listing last updated ^[5] asking \$2,798



§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

