

Register entry, as of 28 October 2026

Listed for sale

Record ID b3f30e8348b8

2008 Mazda Tribute

3.0 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4F2 **CZ961** **4** **8** **K** **M11621**

WMI 1-3

Mazda · FORD MOTOR CO...

DESCRIPTOR 4-8

Tribute · 3.0 L

CHECK 9

Verified

YEAR 10

2008

PLANT 11

Kansas City

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2008	Engine	3.0 L, 6 cylinders
Make	Mazda	Fuel	Gasoline
Model	Tribute	Drive	4WD
Trim	Not in the decode	Maker	FORD MOTOR COMPANY
Body	Sport Utility Vehicle	Plant	Kansas City, Missouri, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mazda/tribute/2008

3 recalls listed by Transport Canada for this model year

Powertrain

2015490 19 Oct 2015

A safety defect may exist in vehicles in which remanufactured automatic transmissions were installed as service replacement parts. The shift lever bolt may not have been torqued to the proper torque specification. If the improperly torqued shift level bolt loosens and backs out, the shift lever may disengage from the transmission without warning, and the transmission may not respond to the shifter selection movement by the operator. This could result in the loss of transmission gear selection, and possible unintended vehicle movement, which would increase the risk of a crash causing injury and/or property damage. Correction: Dealers will inspect, and if necessary, replace the shift lever assembly and/or the shift level bolt torqued to the proper specification.

Steering

2014197 29 May 2014

On certain vehicles, a fault in the Electric Power Steering (EPS) system could result in an immediate loss of power steering assist without warning to the driver. This would unexpectedly increase the steering effort force necessary to steer the vehicle at lower vehicle speeds, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will affect repairs as necessary and will reprogram the EPS controller with updated software. In the event that an EPS fault occurs, this updated software would allow for continued EPS function while displaying visual and audible warnings to the driver until the end of the drive cycle.

Other

2012237 27 Jul 2012

On certain vehicles equipped with a 3.0L V6 engine and speed control, inadequate clearance between the engine cover and the speed control cable connector could result in a stuck throttle when the accelerator pedal is fully or almost-fully depressed. A stuck throttle may result in very high vehicle speeds and make it difficult to slow or stop the vehicle if the transmission is not shifted into neutral. This could result in a crash causing property damage and/or personal injury. Correction: Dealers will replace the rear engine cover fastener, which will raise the cover in the area of the speed control cable to provide adequate clearance between the cover the speed control cable connector.




Listed for the model year, not checked against your VIN. Mazda confirms which apply.
Check your VIN with Mazda Canada or call a Mazda dealer with your VIN.
www.mazdarecalls.ca/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$11,995^[5], the median^[4].



Lowest ask	\$11,995
Middle half	\$11,995 – \$11,995
Median ask	\$11,995
This car	\$11,995

Same model year · 1 live listings · as of 28 Oct 2026

§4 EVENTS

2008	Model year 2008 ^[1] Assembly plant Kansas City, Missouri, United States
27 Jul 2012	Transport Canada recall 2012237 ^[2] Issued for the model year · Other
29 May 2014	Transport Canada recall 2014197 ^[2] Issued for the model year · Steering
19 Oct 2015	Transport Canada recall 2015490 ^[2] Issued for the model year · Powertrain
26 Oct 2026	Listed for sale, Victoria, BC ^[5] King's Auto Sales Ltd. · asking \$11,995
28 Oct 2026	Listing last updated ^[5] asking \$11,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

