

Register entry, as of 28 October 2026

Listed for sale

Record ID 35348d46c979

2007 Mercedes-Benz GL-Class GL450 4-MATIC

4.7 L, 8 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4JG

WMI 1-3

Mercedes-Benz Of North A...

BF71E

DESCRIPTOR 4-8

GL-Class · 4.7 L

5

CHECK 9

Verified

7

YEAR 10

2007

A

PLANT 11

Vance

220406

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	4.7 L, 8 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	GL-Class	Drive	AWD
Trim	GL450 4-MATIC	Maker	MERCEDES-BENZ OF NORTH AMERICA, INC.
Body	Sport Utility Vehicle	Plant	Vance, Alabama, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/gl-class/2007

4 recalls listed by Transport Canada for this model year

Brakes

2022237 6 May 2022

Issue: On certain vehicles, corrosion could cause the brake booster to fail. If this happens, there may be an increase in brake pedal effort and increase the distance needed to stop the vehicle. In rare cases of severe corrosion, the brake booster could separate completely and cause a loss of brakes. Safety Risk: A loss of brakes can increase the risk of a crash. Corrective Actions: Mercedes-Benz advises you to stop driving your vehicle immediately. The company will notify owners by mail and instruct you to contact a local Mercedes-Benz dealership to arrange for towing and an inspection. The dealer will remove the rubber brake booster sleeve and determine whether the vehicle is safe to drive or if it can't be driven and a parts replacement is necessary. Also, depending on the results of the inspection, you may need to return within two years for a re-inspection.

Other

2008242 9 Jul 2008

Certain vehicles may have been programmed with incorrect software calibration data during the manufacturing process. This could affect various functions such as: The electric fuel pump may not receive a signal which, in case of a crash, may prevent the fuel pump from disconnecting as designed; The maximum speed limiter may not be activated; The fuel gauge readings may be incorrect; A stuck fuel-level sensor may not be displayed in the instrument cluster; The speedometer may be out of tolerance which, as a result, may indicate inaccurate vehicle speed; The On-Board Diagnostic (OBD) system may reduce the emission level applicable to the vehicle, causing the Check Engine Light to illuminate incorrectly. Correction: Dealers will reprogram the electronic control module.



Other

2008191 2 Jun 2008

On certain vehicles, trailer hitches, whether installed during vehicle assembly, or sold as an over-the-counter accessory and installed by the dealer, may contain inadequate welds and, as a result, could eventually fail. This could allow the towed unit to separate from the towing vehicle, causing property damage, personal injury or death. Correction: Dealers will repair weld the hitch assembly.

Engine

2007418 21 Dec 2007

On certain diesel powered E320, GL320, ML320 and R320 vehicles, the crankshaft sensor may fail, causing the engine to stall. Engine stalling would result in lost propulsion which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash. Correction: Dealers will replace the crankshaft sensor.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

§3 VALUE

No priced market quote for this vehicle yet.

§4 EVENTS

2007 Model year 2007^[1]
Assembly plant Vance, Alabama, United States

21 Dec 2007 Transport Canada recall 2007418^[2]
Issued for the model year · Engine

2 Jun 2008 Transport Canada recall 2008191^[2]
Issued for the model year · Other

9 Jul 2008 Transport Canada recall 2008242^[2]
Issued for the model year · Other

6 May 2022 Transport Canada recall 2022237^[2]
Issued for the model year · Brakes

29 Nov 2025 Listed for sale, Calgary, AB^[3]
Fine Auto Zone · asking \$7,995

24 Oct 2026 Listing last updated^[3]
asking \$7,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.



SOURCES

- [1] Cardog identity register, decoded from the VIN [3] Live public dealer listings on Cardog, as of 28 Oct 2026
[2] Transport Canada recall database, listed for the model year

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

