

Register entry, as of 28 October 2026

Listed for sale

Record ID 6aee df694a23

2011 Mercedes-Benz R-Class R320 BLUETEC 4-MATIC

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

4JG

WMI 1-3

Mercedes-Benz Of North A...

CB2FE

DESCRIPTOR 4-8

R-Class · 3.0 L

1

CHECK 9

Verified

B

YEAR 10

2011

A

PLANT 11

Vance

127550

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	3.0 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Diesel
Model	R-Class	Drive	AWD
Trim	R320 BLUETEC 4-MATIC	Maker	MERCEDES-BENZ OF NORTH AMERICA, INC.
Body	Sport Utility Vehicle	Plant	Vance, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/r-class/2011

4 recalls listed by Transport Canada for this model year

Brakes

2022237 6 May 2022

Issue: On certain vehicles, corrosion could cause the brake booster to fail. If this happens, there may be an increase in brake pedal effort and increase the distance needed to stop the vehicle. In rare cases of severe corrosion, the brake booster could separate completely and cause a loss of brakes. Safety Risk: A loss of brakes can increase the risk of a crash. Corrective Actions: Mercedes-Benz advises you to stop driving your vehicle immediately. The company will notify owners by mail and instruct you to contact a local Mercedes-Benz dealership to arrange for towing and an inspection. The dealer will remove the rubber brake booster sleeve and determine whether the vehicle is safe to drive or if it can't be driven and a parts replacement is necessary. Also, depending on the results of the inspection, you may need to return within two years for a re-inspection.

Airbag

2016158 13 Apr 2016

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will replace the front driver air bag module.



Fuel system

2011359 4 Oct 2011

On certain vehicles equipped with a diesel engine, the fuel filter assembly may develop a leak from the fuel heater o-ring seal. Diesel fuel spilt on the roadway could endanger other road users by making the roadway unexpectedly slippery. This could ultimately result in a vehicle crash causing property damage and/or personal injury. Correction: Dealers will inspect and, if necessary, replace the diesel fuel filter assembly.

Fuel system

2010375 29 Oct 2010

On certain GL350, ML350 and R350 BlueTEC vehicles, the diesel fuel filter may have an O-ring that was not properly lubricated during assembly, which could lead to a diesel fuel leakage. As a result, diesel fuel may be deposited on the road and create a risk a crash. Correction: Dealers will replace the fuel filter.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.

Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks \$10,900^[4], \$1,048 under the median of \$11,948^[3].



Lowest ask \$10,900

Middle half \$11,424 – \$12,471

Median ask \$11,948

This car \$10,900

Same model year · 2 live listings · as of 28 Oct 2026

OTHER 2011 MERCEDES-BENZ R-CLASS LISTINGS [4]

Richmond, BC · 167,231 km

\$12,995

§4 EVENTS

2011

Model year 2011^[1]

Assembly plant Vance, United States

29 Oct 2010

Transport Canada recall 2010375^[2]

Issued for the model year · Fuel system

4 Oct 2011

Transport Canada recall 2011359^[2]

Issued for the model year · Fuel system

13 Apr 2016

Transport Canada recall 2016158^[2]

Issued for the model year · Airbag

6 May 2022

Transport Canada recall 2022237^[2]

Issued for the model year · Brakes

20 Oct 2026

Listed for sale, Airdrie, AB^[4]

SJL Auto LTD · asking \$10,900



28 Oct 2026 Listing last updated^[4]
asking \$10,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [3] Cardog market quote, same model year, 2 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

