Register entry, as of 29 October 2026 Listed for sale Record ID 09bce9cfd383

2018 Mercedes-Benz GLE-Class GLE400

3.0 L, 6 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4JG	DA5GB	4	J	B	104060
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Of North A…	GLE-Class · 3.0 L	Verified	2018	United States	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.0 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	GLE-Class	Drive	Not in the decode
Trim	GLE400	Maker	MERCEDES-BENZ OF NORTH AMERICA, INC.
Body	Sport Utility Vehicle	Plant	United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/gle-class/2018

7 recalls listed by Transport Canada for this model year

Fuel system

2022741 22 Dec 2022

Issue: On certain vehicles, water could leak into the rear of the vehicle and build up in the spare tire wheel well. If this happens, the fuel pump control unit could short circuit and cause the engine to stall. Note: This problem could cause a check engine light to turn on, a damp carpet in the cargo area and/or the sound of water moving in the spare wheel well while driving. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect for water leaks and install a drain plug in the spare wheel well. The fuel pump control unit will be replaced, if necessary. To reduce the safety risk, you should regularly check for moisture in the cargo area and spare wheel well.

Visual system

2021291 14 May 2021

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Structure

2021170 22 Mar 2021

Issue: On certain vehicles, the plastic panel located between the windshield and the panoramic sunroof may not have been attached correctly during a prior service repair. Over time, the panel could loosen and separate from the vehicle. Safety Risk: A panel that detaches from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front roof panel.

Tires

2021111 2 Mar 2021

Issue: On certain vehicles, the tires may have been cured for too long. As a result, the sidewall could crack or the tread and belts could separate. This could cause a tire failure and lead to sudden loss of air pressure. Note: This recall only affects certain Continental tires, with specific date codes and mold numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to inspect and replace the tires, if necessary.

Accessories

2021041 1 Feb 2021

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to update the head unit software.

Brakes

2018435 17 Aug 2018

On certain vehicles, a problem with the rear brake system may cause gas bubbles to form in the brake fluid. This could cause a soft brake pedal feel and a reduction in brake performance, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will bleed the rear brakes.

1 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/gle-class/2018

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $27,745[4], $1,765 over the median of $25,980[3].

Lowest ask	$19,999
Middle half	$23,988 – $26,999
Median ask	$25,980
This car	$27,745

Same configuration · 29 live listings · as of 29 Oct 2026

OTHER 2018 MERCEDES-BENZ GLE-CLASS LISTINGS [4]

Oakville, ON · 121,977 km	$28,588
Regina, SK · 142,797 km	$27,959
London, ON · 151,801 km	$24,995
Mississauga, ON · 158,042 km	$20,888
Toronto, ON · 128,181 km	$24,999

§4 EVENTS

2018	Model year 2018[1] Assembly plant United States
3 Aug 2018	Transport Canada recall 2018408[2] Issued for the model year · Structure

17 Aug 2018	Transport Canada recall 2018435[2] Issued for the model year · Brakes
1 Feb 2021	Transport Canada recall 2021041[2] Issued for the model year · Accessories
2 Mar 2021	Transport Canada recall 2021111[2] Issued for the model year · Tires
22 Mar 2021	Transport Canada recall 2021170[2] Issued for the model year · Structure
14 May 2021	Transport Canada recall 2021291[2] Issued for the model year · Visual system
22 Dec 2022	Transport Canada recall 2022741[2] Issued for the model year · Fuel system
25 Sep 2026	Listed for sale, Abbotsford, BC[4] Fraser Valley Pre-Owned · asking $27,745
28 Oct 2026	Listing last updated[4] asking $27,745

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same configuration, 29 live listings, as of 29 Oct 2026
[4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.