Register entry, as of 28 October 2026 Listed for sale Record ID 1052fda178ec

2013 Mercedes-Benz GL-Class GL450 4MATIC

4.7 L, 8 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

4JG	DF7CE	7	D	A	106456
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Of North A…	GL-Class · 4.7 L	Verified	2013	Vance	Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	4.7 L, 8 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	GL-Class	Drive	AWD
Trim	GL450 4MATIC	Maker	MERCEDES-BENZ OF NORTH AMERICA, INC.
Body	Sport Utility Vehicle	Plant	Vance, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/gl-class/2013

4 recalls listed by Transport Canada for this model year

Brakes

2022237 6 May 2022

Issue: On certain vehicles, corrosion could cause the brake booster to fail. If this happens, there may be an increase in brake pedal effort and increase the distance needed to stop the vehicle. In rare cases of severe corrosion, the brake booster could separate completely and cause a loss of brakes. Safety Risk: A loss of brakes can increase the risk of a crash. Corrective Actions: Mercedes-Benz advises you to stop driving your vehicle immediately. The company will notify owners by mail and instruct you to contact a local Mercedes-Benz dealership to arrange for towing and an inspection. The dealer will remove the rubber brake booster sleeve and determine whether the vehicle is safe to drive or if it can't be driven and a parts replacement is necessary. Also, depending on the results of the inspection, you may need to return within two years for a re-inspection.

Engine

2018217 27 Apr 2018

On certain vehicles equipped with the Active Curve System (ACS), the oil in the ACS's reservoir could start foaming under certain dynamic driving situations in combination with an oil level below minimum. The oil foam could leak out of the oil reservoir through the vent holes in the sealing cap and spray onto hot surface components of the exhaust system. This could increase the risk of fire causing injury and/or damage to property. Correction: Dealers will inspect the ACS reservoir for proper oil level and replace the sealing cap with an updated part.

Airbag

2017145 15 Mar 2017

On certain vehicles, an update provided between de 3rd and 5th of December 2016 to the vehicle control unit may have been incorrectly applied. This could affect the proper function of various safety systems such as airbag deployment sequence, seatbelts recognition status, speed limiter setting and others. These conditions could increase the risk of injury to the occupants in the event of a crash. Correction: Dealers will update the affected control units.

Seats and restraints

2013138 26 Apr 2013

On certain vehicles, seatbelt anchors for the second row seats may not have been sufficiently tightened during vehicle assembly. Failure of the seatbelt anchor to restrain the seat occupant during a crash could increase the risk of personal injury. Correction: Dealers will inspect and, if necessary, tighten the second row seatbelt anchor bolts.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $13,500[4], $5,242 under the median of $18,742[3].

Lowest ask	$13,500
Middle half	$17,748 – $20,344
Median ask	$18,742
This car	$13,500

Same model year · 6 live listings · as of 28 Oct 2026

OTHER 2013 MERCEDES-BENZ GL-CLASS LISTINGS [4]

Toronto, ON · 135,000 km	$18,490
Richmond, BC · 127,037 km	$18,995
Red Deer, AB · 124,584 km	$20,794
Olds, AB · 124,584 km	$20,794
Innisfail, AB · 124,584 km	$20,794
Canmore, AB · 124,584 km	$20,794

§4 EVENTS

2013	Model year 2013[1] Assembly plant Vance, United States
26 Apr 2013	Transport Canada recall 2013138[2] Issued for the model year · Seats and restraints
15 Mar 2017	Transport Canada recall 2017145[2] Issued for the model year · Airbag
27 Apr 2018	Transport Canada recall 2018217[2] Issued for the model year · Engine

6 May 2022	Transport Canada recall 2022237[2] Issued for the model year · Brakes
5 Oct 2026	Listed for sale, Edmonton, AB[4] Redline Motors · asking $13,500
28 Oct 2026	Listing last updated[4] asking $13,500

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 6 live listings, as of 28 Oct 2026
[4] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.